

REF:

ASSIGNMENT

Front: _____ Date: _____

Estimate: _____

OD / ~~TP~~ / TP RES / CD RES / EVA / INV / MV

To In _____ Vehicle No: _____

at W _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: Tlevch had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: XE8678G Yr Regn: 2023, Oct.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hino FYIEUKA C.D. 12913Colour: White A/C: Insured / Std / NI / NASp. Reading: 41684 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHDYIEUKXXX14817

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim orTyre Size: F: 295/80R22.5R: 295/80R22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 18/12/24.Survey held at Premium Carz.

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Front x/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Chrm

COE Expiry: _____

Estimate given during: Yes ☒ No ☐

st Survey: Yes ☒ No ☐

MV: 3251K (Depreciation (a))

PV: 64.91K 38k x 8.8yr = 325k

Nett: 2601K

Date/Time, File Pass to?

☐: Preli. Report

Days Of Repair: _____

1)

☐: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐: Site Insp (\$ _____)

Survey Fee: _____

Transportation: _____

3 + RS. \$1

Photos

Others

Report Format: _____

Report Form / L.P. / C.D.

☐: Interview (\$ _____)☐: Tech. Inve (\$ _____)



CHINA TAIPING INSURANCE (S'PORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Our Customer : SHIN KHAI CONST PTE LTD

Vehicle No : XE8678G
Model : HINO FY1EUKA 34 TON
8X4MT

Manufacture Year : 2023

Date of Accident : 07-12-24

Total Estimate Repair Days : 6 days

Total Pages : 2

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks
A.	Spare Parts				
1	Front Head Lamp LH <i>?</i>	1		\$1,275.30	<i>sk ?</i>
2	Front Bumper <i>Del d</i>	1		\$1,090.00	<i>✓</i>
	Front bumper lower grille <i>new</i>				
3	Front bumper reinforcement <i>new</i>	1		\$535.00	<i>+</i>
4	Front Grille <i>new</i>			\$637.65	<i>+</i>
5	Front bumper reflector - LH -ROUND <i>lot</i>	1		TBA	<i>-</i>
6	Front bumper side garnish - LH <i>lot</i>	1		TBA	<i>✓</i>
7	Front fender - LH <i>new</i>	1		\$681.25	<i>+</i>
8	Front support panel <i>new</i>	1		\$1,912.00	<i>+</i>
9	Front stay panel <i>lot</i>	1		\$74.50	<i>✓</i>
			Total	\$6,205.70	
			Less 10%	-\$620.57	
			Sub Total 1	\$5,585.13	
A.	Spare Parts (S/Nett)				
1	Bumper Bracket - LH <i>new</i>	1		\$165.00	<i>+</i>
			Sub-Total 2	\$165.00	
			Total for Parts	\$5,750.13	

Date : 17-12-24

CHINA TAIPING INSURANCE (S'PORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

Attn: Motor Claims Department
Tel: 6389 6111

Our Customer : SHIN KHAI CONST PTE LTD

Vehicle No : XE8678G

Model : HINO FY1EUKA 34 TON
8X4MT

Manufacture Year : 2023

Date of Accident : 07-12-24

Total Estimate Repair Days : 6 days

Total Pages : 2

Re: Repair Estimate For Third Party Claim against SNH976B

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks
B.	Labour				
1	Panel Beating to affected areas.			\$600.00	300
2	Spray painting all affected parts & areas.			\$600.00	200
3	Check wiring & re-focus headlight			\$120.00	30
	Total Labour			\$1,320.00	
	Total Repair Cost			\$7,070.13	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Li
2/5 18/12/24
03 Rg

Yours faithfully,

余



Candice Yee

f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No