



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

STRIDES PREMIER AUTOMOTIVE SERVICES PL INV No. AC2500846
60 WOODLANDS INDUSTRIAL PARK E4 INV Date 10/02/2025
SINGAPORE 757705 Reference CS/SMR24120386/Tqp3m4
ATTN: HUA YEN Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. SNT 2885D
Insured Veh. SHB 1120A
Claim No. TAX/12/24/2084
Policy No.
Accident Date 22/12/2024
Inspection Date 26/12/2024

Description	Total
Survey Inspection	128.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

SML



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES PREMIER AUTOMOTIVE SERVICES PL		Ref:	CS/SMR24120386/Tqp3m4 (N)
60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Date:	10/02/2025
ATTN: HUA YEN		Code:	SMR
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 1120A	Veh. Inspected	SNT 2885D
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/12/24/2084	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	26/12/2024
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA SIENTA HYBRID	c.c	1490
Engine No.	HIDDEN	Year of Reg.	2024
Chassis No.	JTDBBBA360L001837	Colour	BLACK
Odometer	17515 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/65R15	TOYO	6 mm
L/H Front Tyre	185/65R15	TOYO	6 mm
R/H Rear Tyre	185/65R15	TOYO	6 mm
L/H Rear Tyre	185/65R15	TOYO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	22/12/2024	Inspection Date	26/12/2024
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SNT 2885D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
1	MIRROR ASSY, OUTER (SN)	CRACKED	1,681.50	1,681.50
1	COVER, OUTER MIRROR, (SN)	TO REPAIR SEE LABOUR	173.30	-
			1,954.80	1,711.50
LABOUR				
	CHECK WIRING SYSTEM.		198.00	198.00
	REPL ACC AFF AREA. INCLUSIVE OF THE REPAIR OF COVER, OUTER MIRROR.		1,584.00	396.00
	RESPRAY ACC AFF AREA.		1,312.00	250.00
			3,094.00	844.00
GRAND TOTAL			5,048.80	2,555.50
RECOMMENDED COST OF REPAIRS				2,555.50

Report Ref No. CS/SMR24120386/Tqp3m4(N)

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	23/12/2024 11:03 (SGT)
Reported by	Actual Driver
Date of Accident	22/12/2024 09:15 (SGT)
Exact Location of Accident	Ophir Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNT2885D
-----------------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	GRAB RENTALS PTE LTD
Company Reg No	2XXXXX200G
Email Address	
Mobile Phone No	
Alternative Phone No	

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Sienta
Variant	HYBRID STANDARD
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1490
Vehicle Fuel	Petrol-Electric
First Registration Date	-
Chassis no	JTDBBBA360L001837
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	India International Insurance Pte Ltd
Policy Number / Cover Note Number	D21MFL0000447_03

DRIVER

Name of Driver	LIM KWANG NYAR (LIN GUANGYING)
NRIC No	SXXXX039D
Date Of Birth	
Occupation	Outdoor
Driving Pass Date	26/01/1996
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	28 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	-
Alt. Phone Number	-
Email Address	-
Address	-
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	UNKNOWN
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Rochor Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18002949999
Alt. Police Station Phone No	(Fax) +65-63918583
Police Station Address	11 Kampong Kapur Road Singapore 208678
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

AS PER POLICE REPORT NO: T/20241222/2026

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHB1120A
Vehicle Manufacturer Toyota
Vehicle Model PRIUS HYBRID 1.8 CVT
Vehicle Variant -
Vehicle Colour -
Vehicle Category Taxi
Name of Driver -
Contact Number -
Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please correctly report the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorized Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
 - (ii) investigating the accident and/or my claims.
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports, or notices to me, which could involvedisclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (Collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

22 DEC 2024
1300HRS



OPHIR ROAD
A-SNT2885D
B-SHB1120A

Describe Circumstances of the Accident

AS PER POLICE REPORT NO: T/20241222/2026

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time



Driver's Signature (If driver is not the policyholder) / Date
& Time
22 DEC 2024
1300HRS

 *caravintan*

Witnessed by Reporting Centre
Personnel



**SINGAPORE
POLICE FORCE**



T/20241222/2026

1 of 3

Police Station Of Origin:
Rochor N.P.C
11 Kampong Kapur Road SINGAPORE
208678
Tel No: 1800-2949999

Report No. T/20241222/2026

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 22/12/2024 11:39	Vide Report No.:	Station Diary No.: 44
--	------------------	--------------------------

Informant's Particulars

Name of Informant: LIM KWANG NYAR		Address: 15 FARRER PARK ROAD #29-41 SINGAPORE 210015	
ID Type / ID No.: NRIC NO / S7311039D		Contact No.:	Mobile: 98280332
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 51	Date of Birth: 24/03/1973	Type of Informant: Driver
Race: Chinese		Language:	
Occupation: PRIVATE HIRER DRIVER		Driving Licence Information: Class: 3,4	Date of Expiry:

General Information of the Accident

Type of Accident: Non-Injury	Drink Drive: No	Date/Time of Accident: 22/12/2024 09:15	Type of Location: Junction
Location: OPHIR RD			
Weather: Clear	Road Surface: Dry		
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Side Swipe - Same Direction			Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Conditio	No of Passenger
SHB1120A	Taxi				No Damage	1
SNT2885D	Motor car				Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20241222/2026

Police Station Of Origin:
Rochor N.P.C
11 Kampong Kapur Road SINGAPORE
208678
Tel No: 1800-2949999

2 of 3

Report No. T/20241222/2026

CONTINUATION OF REPORT

Driver			
Name	MD JOHAN		ID No. S2013901C
Related Vehicle	NIL		Contact No. 98635423
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL
Driver			
Name	LIM KWANG NYAR		ID No. S7311039D
Related Vehicle	NIL		Contact No. 98280332
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Class: 3,4 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL	Degree of	NIL

Brief Details.

On 22/12/2024 at about 0915hrs, I was driving my vehicle registration plate number SNT2885D with one passenger along Ophir Road towards ECP on the 4th lane. Subsequently, a taxi registration plate number SHB1120A from 3rd lane wanted to turn left towards Beach Road, side swept and hit right side of my vehicle.

Both of them drove forward and stopped at the left side of the road along Ophir Road. I alighted from my vehicle and discovered my right-side mirror was damaged. I made a check on the taxi and no damages. Both of us exchange particulars and decided to claim insurance. I wish to inform that there is built in car camera. Lastly, no one was injured.

 **SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Rochor N.P.C
11 Kampong Kapur Road SINGAPORE
208678
Tel No: 1800-2949999

T/20241222/2026
3 of 3
Report No. T/20241222/2026

CONTINUATION OF REPORT

Signature of Officer Recording The A / SGT 2 MUHAMMAD SHAHFIEUDIN BIN SIRAJUDDIN 	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 22/12/2024 11:39
Officer In Charge Of Case: TP / GIA / INSP (1) BOON YEN KIAN Contact No.: 65472079	Classification Of Case:


NP168



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. : SNT 2885D



PHOTOGRAPHS FOR VEHICLE NO. : SNT 2885D



PHOTOGRAPHS FOR VEHICLE NO. : SNT 2885D



PHOTOGRAPHS FOR VEHICLE NO. : SNT 2885D



PHOTOGRAPHS FOR VEHICLE NO. : SNT 2885D





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SNT 2885D

