

SIN HOCK LEE MOTOR REPAIR

Page 1

UEN NO. 24928500B GST NO. M90366191A

BLK 51 UBI AVENUE 1 #01-09

PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Tel No. : 6282 6184 Fax: 6287 5977

YSE GLOBAL PTE LTD
NO. 2 TUAS VIEW SQUARE
SINGAPORE 637576

Estimate : EST2412002

Date : 24/12/2024

Vehicle Num. : GBH7342B

Make/Model : TOYOTA DYNA 150 M

Chassis No : JTFAT35Y60K211310

Accident Date : 21/12/2024

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS::

1	1	FRONT GRILLE <i>Cna</i>	572.60	572.60 ✓
2	1	FRONT GRILLE EMBLEM 'TOYOTA' LOGO <i>u n</i>	94.70	94.70 ✓
3	9	FRONT GRILLE CLIP SET <i>u n</i>	8.50	76.50 ✓
4	1	FRONT HEAD LAMP RH <i>Cna</i>	1,000.50	1,000.50 ✓
5	1	FRONT BUMPER <i>ToFA</i>	822.70 <i>801.20</i>	822.70
6	2	FRONT BUMPER BRACKET <i>o/s bumper</i>	255.00	510.00 <i>120</i>
6	1	FRONT DOOR MIRROR RH <i>u n</i>	296.00	296.00 ✓
7	1	FRONT DOOR STEP RH <i>u n</i>	300.00	300.00 ✓

Sub-Total List Parts S\$:

3,673.00

Discount 25%

-918.25

Total Parts S\$:**2,754.75****LABOUR :**

1	1	TO CHECK & RECTIFY WIRING SYSTEM	80.00	<i>20</i>
2	1	TO RUST PROOF ON AFFECTED AREAS	90.00	<i>17</i> ✓
3	1	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE BODYPARTS, REPAIR, RE-ALIGN & DAMAGES CONSISTENT TO THE ACCIDENT	840.00	<i>300</i>
4	1	TO RE-SPRAY PAINTING ON THE CHANGED BODYPARTS, REPAIRED PORTION, & WHERE CONSISTENT TO THE ACCIDENT	800.00	<i>550</i>

Labour Total S\$:**1,810.00****E. & O.E.**

Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Sub-Total S\$: 4,564.75**GST 9% 410.83****Total S\$: 4,975.58****for SIN HOCK LEE MOTOR REPAIR**

Note: This is only an estimate based on our preliminary inspection and does not cover additional labour time or which may be required after the work has begun.

Date:

9-2925-30
252
2193.98
870
3063.98
202
2000