



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: MARCUS XIAO

Ref: CS/INC24120402/Unh3m4(N)

Date: 09/01/2025

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 1591J	Veh. Inspected	SLG 7471Z
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1309620-001	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	26/12/2024

#### 2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL 1.5X (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11204736	Colour	SILVER
Odometer	142008 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	YOKOHAMA	6 mm
L/H Front Tyre	215/60R16	YOKOHAMA	6 mm
R/H Rear Tyre	215/60R16	YOKOHAMA	6 mm
L/H Rear Tyre	215/60R16	YOKOHAMA	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  
DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	21/12/2024	Inspect Date / Time	30/12/2024 ( 11:31 AM )
Survey held at	M-TECH MOTOR SERVICES BLK 9005 TAMPINES STREET 93 #01-252, TAMPINES INDUSTRIAL PARK A SINGAPORE 528839		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------