

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTChina Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909**Our File No:** CS/CT124120413/TQH3E2**Date:** 07/01/2025REFERENCE

Insured/Claimant:	TIPSON INDUSTRIAL TRADING P/L	Policy No:	DMCVSNW00013652407
Date of Loss:	18/12/2024	Nature of Claim:	OD
		Claim No:	SNM24D207125/C01/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE7776Z		
Make & Model:	PEUGEOT PARTNER, 1.6 HDI ETG LWB (A)	Engine No:	10JBFR0023443
Reg. Date:	29/03/2016 (Man. Year: 2015)	Chassis No:	VF37F9HF8FJ884518
Colour:	Silver	Odometer:	142410 km
Engine Capacity:	1560 cc		
Market Value/New Car Price:	S\$12,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	0.00	0.00	0.00	
- Excess (\$\$)	0.00	450.00	-450.00	
Nett Amount (\$\$)	0.00	-450.00	450.00	

INSPECTION

Date of Assignment:	27/12/2024	Present Location:	Automotive Repair Centre Pte Ltd (HQ)
Date Inspected:	27/12/2024	Inspected At:	Automotive Repair Centre Pte Ltd (HQ) 48 Toh Guan Road East, #02-146 Enterprise Hub Singapore 608586
Estimated Period of Repair:	0.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

TOTAL LOSS ASPECT

Market Value :	\$12,000.00
OMV :	\$18,749.00
PARF Rebate (1) :	\$ 0.00
Quota Premium Paid :	\$46,502.00
COE Rebate (2) :	\$ 5,825.00
Total Rebate (1) + (2) = :	\$ 5,825.00

The total amount incurred will be Market Value \$12,000.00 minus Total Rebate \$5,825.00 = \$6,175.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 07 Jan 2025)	
Parts:	N/A	PEUGEOT PARTNER 1.6 HDI ETG LWB (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE7776Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >