

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

4S INCOME IN		Affiliated to Federation Internationa	le Des Experts En	Automobile
13 INCOME IN	NCOME INSURANCE LTD		Ref:	CS/INC24070039/Anh3
	75 BRAS BASAH ROAD INCOME CENTRE SINGAPORE 189557		Date:	25/09/2024
INCOME C			Code:	INC
1.		Policy Particulars :- T		IM
Insured Ve	h. :	SLV 3062T	Veh. Inspected	GP 93P
Policy No.	-	-	Coverage	0
Claim No.		MT/1283982-001	Excess	\$0.00
Assign Fro	om [	RAJESWARY D/O DORAISAMY	Assign Date	02/07/2024
2.		Vehicle	Details	
Make & Mo	odel	TOYOTA HIACE DX	C.C	2754
Engine No.		1GD8346343	Year of Reg.	13/05/2019
Chassis No	0. (	GDH2012003493	Colour	WHITE
Odometer		169991 KM	Steering	IN ORDER
Brakes	- 1	N ORDER	General	GOOD
Modificatio	on(s)	RIMS: NIL		
3.		Conditions	s of Tyres	
		Size	Make	Balance (mm)
R/H Front 1	Tyre	195 R15C	MICHELIN	6
L/H Front T	Гуге	195 R15C	MICHELIN	6
R/H Rear T	yre	195 R15C	MICHELIN	6
L/H Rear Ty	yre	195 R15C	MICHELIN	6
4.		Description	of Damages	
HE VEHICLE S	SUSTAINE	D DAMAGES AT THE FRONT O/S PC	ORTION.	
	DETAILS			
AMAGES SEE		General In	formation	
AMAGES SEE		General In: 27/06/2024	Inspection Date	04/07/2024 (13:42)
OAMAGES SEE	Date 2		T	04/07/2024 (13:42)
DAMAGES SEE  5.  Accident D	Date 2	27/06/2024 CHIA AUTO SERVICES PTE LTD 23 KAKI BUKIT AVENUE 4 #02-03A AAS KAKI BUKIT CENTRE	Inspection Date	04/07/2024 (13:42)
5. Accident D Survey held  5a. THE INSPEC	Date 2	27/06/2024 CHIA AUTO SERVICES PTE LTD 23 KAKI BUKIT AVENUE 4 #02-03A AAS KAKI BUKIT CENTRE SINGAPORE 415933	Inspection Date  arks  EJUDICE" BASIS.	

ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days