

REF:

### ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estim: \_\_\_\_\_

OD / TP RES / CD RES / EVA / INV / MV

To in \_\_\_\_\_ Vehicle No: \_\_\_\_\_

at \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client Record)

Make of Val: \_\_\_\_\_

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Scan: \_\_\_\_\_ Consistent? : Yes or No

Est. Repair: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SMK348K Yr Regn: 2019, March

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Noah Hybrid 1797

Colour: Black A/C: Insured / Std / NI / N.A

Sp. Reading: 199317 T/Radio: Insured / Std / NI / N.A

Eng/No: \_\_\_\_\_

C/No: ZWR800367519

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Habilead

Front Rear

R/Bal. ob mm R/Bal. ob mm

L/Bal. ob mm L/Bal. ob mm

D.O.A. \_\_\_\_\_ D.O.I. 15/01/25

Survey held at NSI

Des. of Damages: Frt / Rear / O/S / I/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP claim</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey</u>
	<u>MV: 90k</u>
	<u>PV: 36k</u>
	<u>Nett: 54k</u>

Date/Time, File Pass to?  : Prel. Report

1)  : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

3 + RS. \$1

Photos

Other

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech. Inve (\$)

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

ZAINI BIN ABDUL SAMAT  
 101 PASIR RIS ST 12 #04-11  
 SINGAPORE 510101

Contact : 91546969

## TAX INVOICE

Repair Code : CLM18510  
 Date in : 14/12/2024  
 Vehicle Num. : SMK348K  
 Model : TOYOTA NOAH HYBRID 1.8X CVT  
 Chassis/Eng# : ZWR800367519/2ZR0D06928

### Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>dam</i>	1	841.20	✓ 841.20
REAR BUMPER END SEAL COVER RH <i>new</i>	1	138.00	+ 138.00
REAR BUMPER RH REFLECTOR <i>could</i>	1	141.20	✓ 141.20
REAR BUMPER RH SIDE RETAINER <i>could</i>	1	86.10	✓ 86.10
Subtotal before discount			1,206.50
Percentage discount 25%			301.63
<b>Sub-total 1</b>			<b>904.88</b>
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	30 50.00
REAR BUMPER REVERSE SENSOR <i>new</i>	1	280.00	+ 280.00
REAR BUMPER RH REFLECTOR CHROME COVER <i>could</i>	1	280.00	<del>180</del> 280.00
Subtotal before discount			180 610.00
Percentage discount 0%			0.00
<b>Sub-total 2</b>			<b>610.00</b>
<b>Parts-total</b>			<b>1,514.88</b>

### LABOUR

- To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.

- the Repairer of the following:**
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

**Labour Total** 1,480.00  
**Parts & Labour Total** 2,994.88

*Adnan L  
 h/c 15/01/25  
 02 hrs*