



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: MARCUS XIAO

Ref: CS/INC24120424/Uvh3m4(N)

Date: 08/01/2025

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 5Y	Veh. Inspected	SLP 2918M
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1309514-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	26/12/2024

#### 2. Vehicle Particulars & Condition

Make & Model	RENAULT MEGANE GT LINE	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VF1RFB00656602468	Colour	GREY
Odometer	104924 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/45 ZR17	DUNLOP	6 mm
L/H Front Tyre	205/45 ZR17	DUNLOP	6 mm
R/H Rear Tyre	205/45 ZR17	DUNLOP	6 mm
L/H Rear Tyre	205/45 ZR17	DUNLOP	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	21/12/2024	Inspect Date / Time	27/12/2024 ( 10:45 AM )
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------