

REF: CS/INC24120425/Aqh3

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / TP RES / OD RES / EVA / INV / MVTo in Vehicle No: _____at W/O 12/10/15

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vek: _____

(Policy Condition)

Remark: Vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repair: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKT9076L Yr Regn: 2015, JuneType: M. Car M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3 HB. C.D. 1496Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 12190 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BM44A8G0300493.Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16R: 205/60R16

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Delmax

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 27/12/24Survey held at HP Perfect.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction

TP INC

LS \$3450, 3 days (Red \$9189.28, 73%)

MV: 1210.PV: 6.5KNett: 5.5K

COE Expiry: _____

Estimate given during: Yes (✓)

1st Survey: No (✓)

697H.

Date/Time, File Pass to?

☐

: Preli. Report

1) 21/03 Typist☐

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3Resurvey No. of Trip: 2

Survey Fee:

Transportation:

3 + P.S. 81

Photos

Others

Addl Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Inve (\$ _____)Report Format: TP

Report Form: _____