

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	INCOME INSURAN		Ref:	CS/INC24120426/Aqh3m4(N)	
	75 BRAS BASAH R INCOME CENTRES		Date:	26/03/2025	
	ATTN: ASTER QUE	EK		Code:	INC
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBC 6189K	Veh. Inspected	d	SMC 4647M
	Policy No.		Coverage (\$)		0.00
	Claim No.	MT/1309668-002	Excess (\$)		0.00
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		27/12/2024
2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA PRIUS C HYBRID	c.c		1497
	Engine No.	HIDDEN	Year of Reg.		2018
	Chassis No.	JTDKD3B3601614082	Colour		BLACK
	Odometer	311927 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195/55R15	ZEXTOUR		6 mm
	L/H Front Tyre	195/55R15	ZEXTOUR		6 mm
	R/H Rear Tyre	195/55R15	ZEXTOUR		6 mm
	L/H Rear Tyre	195/55R15	ZEXTOUR		6 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	24/12/2024	Inspect Date /	Time	27/12/2024 (12:58 PM)
	Survey held at	JL PERFECT AUTOWORK PTE	LTD		
	8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		12 Work	ing Days