

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN		Ref:	CS/INC24120427/Avh3e2(N)		
	75 BRAS BASAH R INCOME CENTRES		Date:	25/03/2025		
	ATTN: FIONA SHE	N		Code:	INC	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	PC 9774K	Veh. Inspected	t	GBD 1588U	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1309793-001	Excess (\$)		0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		27/12/2024	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA DYNA	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	JTFAT35Y60K203210	Colour		SILVER	
	Odometer	181437 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15C	ODYKING		6 mm	
	L/H Front Tyre	195 R15C	ODYKING		6 mm	
	R/H Rear Tyre	155 R12C	CONDOR		6 mm	
	L/H Rear Tyre	155 R12C	CONDOR		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	23/12/2024	Inspect Date /	Time	27/12/2024 (01:19 PM)	
	Survey held at JL PERFECT AUTOWORK PTE LTD					
	8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					
	•					