

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/GA/24/20444/Urp3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: - SHD6428U

at Workshop m/s SMC

of _____

Insured: SKP 5495C

Policy No. _____

Claims No. CLMOMVP000001629


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 1.31% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

389k

Vehicle: IN / OUT

Date: _____ Person Contacted: LIA 7120

Veh No: SHD6428U

Yr Regn: 19/12/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA / Hybrid

Make: Toyota Prius c.c 1798

Colour: Maroon A/C: Insured / Std / NI / NA

Sp.Reading: 760762 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDBK3FU X03577003

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Green trac

Front 6 Rear 6

R/Bal. mm R/Bal. mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 27/1/24 D.O.I. 30/1/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

21C Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
9/1/25	Call out 18-12-2025 P/P 81260 intend poh sue (red 11,266.20, 89%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 4

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

2)

Add Fee: ☐ : Site Insp (\$)

Transportation: _____

☐ : Interview (\$)

Photos

☐ : Tech. Invs (\$)

Others

☐ : Weekend (\$)

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$)

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	369K

Vehicle Details

Vehicle No.:	SHD6428U
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Dec 2024
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR8263848
Chassis No.:	JTDKB3FUX03577003
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	19 Dec 2017
First Registration Date:	19 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2025
PARF Rebate Amount:	\$3,000.00

Intended COE Rebate Details

COE Expiry Date:	18 Dec 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,159.00
COE Rebate Amount:	\$4,120.00
Total Rebate Amount:	\$7,120.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 30 Dec 2024

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	27/12/2024 15:03 (SGT)
Reported by	Actual Driver
Date of Accident	27/12/2024 09:20 (SGT)
Exact Location of Accident	458 Hougang Ave 10, Singapore 530458
Additional Location Information	NEAR BLK 458
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6428U
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	Strides Premier Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	sparc@stridespremier.com.sg
Mobile Phone No	(Phone) +65-65446676
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800
Vehicle Fuel	-
First Registration Date	-
Chassis no	-
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Policy Number / Cover Note Number	D-24102275MFSH

DRIVER

Name of Driver	SIM KWANG IMK
NRIC No	SXXXX995Z
Date Of Birth	26/09/1952
Occupation	Outdoor
Driving Pass Date	08/09/1970
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	54 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-65446676
Alt. Phone Number	-
Email Address	sparc@stridespremier.com.sg
Address	11
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	CHINESE FEMALE
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS TRAVELLING STRAIGHT ALONG HOUGANG AVE 10 WITH ONE PASSENGER (FEMALE CHINESE) ON BOARD. SUDDENLY A VEHICLE SKQ5495C CAME OUT FROM THE PARKING LOT WITHOUT PROPER LOOK OUT AND HIT THE RIGHT REAR PORTION OF MY TAXI.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKQ5495C
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

Veh A - SHD64284
B - SKQ 5495C

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder)
/ Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

[Signature]

Actual Driver's Signature (if driver is not the policyholder) / Date & Time *27/12/2024*

[Signature] 27.12.2024

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan

8 Jun 2022

SMRT Accident Vehicle Repair Estimates

SMRT Automot
60 Woodlands I
FAX Number :
Estimator Telep
Accident Repor

Date Generate
User ID

TP
84

Great American

Section A - Accident Details

Registration Number	SHD6428U
Case Reference Number	TAX/12/24/2092
Registration Date	19/12/17
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	SIM KWANG IMK
Type of Accident	Side Swipe
Accident Date and Time	27/12/24 9:20 AM
Accident Reported Date and Time	27/12/24 2:16 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	ACGJ24120089
Special Instruction to ARC,if any	TP/GREAT AMERICAN
Prepared Date and Time	27/12/24 3:09 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,018.00	\$0.00
Total Spray Cost	\$1,794.00	\$0.00
Total Spare Part Cost	\$5,396.55	\$0.00
Total Other Cost	\$740.00	\$0.00
TOTAL COST	\$8,948.55	\$0.00
Lump Sum Total	\$8,950.00	\$0.00
Number of Repair Days	6.0	
Prepared / Adjusted By	Mun San #	
ARC / Surveyor Sign Off Date		
Signature	SW	<input type="checkbox"/>
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

AUTOMOTIVE

to Consultants hence notify
the Repairer of the following: **SMRT Accident Vehicle Repair Estimates**

- To recovery before/after spray painting
- To display damaged part (s) for recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be rechecked and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Section D - Details of Repair Estimates

SMRT Auto
60 Woodlands I
FAX Number :
Estimator Telep
Accident Repor

Date Generate

User ID

not allowed
in
any
30/1/24
P/P # 1260
4 days

@ 1.40pm

Zhang Hui

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION RH	\$1,018.00	200
Total Labour	\$1,018.00	500

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	200
TO RESPRAY REAR FENDER RH	\$378.00	200
TO RESPRAY REAR DOOR RH	\$378.00	200
TO RESPRAY ROCKER PANEL MOULDING	\$220.00	11 X
TO RESPRAY RIM	\$220.00	50
TO RESPRAY FILLER RR BUMPER RH	\$220.00	50
Total Spray Painting & Panel Beating	\$1,794.00	50

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	
TO TRANSFER DOOR MECHANISM	\$120.00	
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	
TO REPLACE SUNDRY PARTS	\$100.00	
Total Other Costs	\$740.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Appr
		7585047910	MOULDING ASSY, BODY ROCKER PANEL, RH	1.00	\$649.10	25.00	\$486.83	Replace	11 X
		5215947913	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.17	Replace	12 X
		5246247030	PAD, RR BUMPER, RH & LH, 1	2.00	\$4.30	25.00	\$6.45	Replace	11 X
		5246247020	PAD, RR BUMPER, RH & LH, 2	2.00	\$4.30	25.00	\$6.45	Replace	11 X
		5246247010	PAD, RR BUMPER, RH & LH, 3	2.00	\$4.30	25.00	\$6.45	Replace	11 X
		5246147010	PAD, RR BUMPER, CTR	3.00	\$2.50	25.00	\$5.63	Replace	11 X
		5257547040	RETAINER, RR BUMPER, RH	1.00	\$127.40	25.00	\$95.55	Replace	11 X
		5216116010	CLIPS PIECE, FRT BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	11 X
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$623.50	25.00	\$467.63	Replace	11 X
		5256547900	FILLER, RR BUMPER, RH	1.00	\$168.60	25.00	\$126.45	Replace	12 X
		8155147281	LENS & BODY, REAR COMBINATION LAMP, RH	1.00	\$489.00	25.00	\$366.75	Replace	11 X
		8158147010	LENS & BODY ASSY, RR BUMPER, RH	1.00	\$544.40	25.00	\$408.30	Replace	11 X
		8149747020	COVER, REAR COMBINATION LAMP, RH	1.00	\$69.90	25.00	\$52.43	Replace	11 X
		6700347210	PANEL SUB-ASSY, REAR DOOR, RH	1.00	\$1,401.70	25.00	\$1,051.28	Replace	12 X

SMRT Accident Vehicle Repair Estimates

SMRT Automot
60 Woodlands I
FAX Number :
Estimator Telep
Accident Repor

Date Generate

User ID

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Appr
		6875020122	HINGE ASSY, REAR DOOR , UPPER RH	1.00	\$107.00	25.00	\$80.25	Replace	11X
		6877052031	HINGE ASSY, REAR DOOR , LOWER RH	1.00	\$93.90	25.00	\$70.43	Replace	11X
		6863047050	CHECK ASSY, REAR DOOR	1.00	\$199.40	25.00	\$149.55	Replace	11X
		6921147021A1	DOOR OUTER HANDLE REAR , RH	1.00	\$105.50	25.00	\$79.13	Replace	11X
		6160147150	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$943.10	25.00	\$707.33	Replace	R X
		6563747060	LINER, REAR FENDER , RH	1.00	\$151.10	25.00	\$113.32	Replace	11X
		4261147450	WHEEL, DISC	1.00	\$2,036.30	25.00	\$1,527.23	Replace	R X
		4245076020	HUB & BEARING ASSY WITH SPEED SENSOR , REAR AXLE , RH & LH	1.00	\$644.10	25.00	\$483.08	Replace	11X
			STICKER LOGO (RR DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	new
Total					\$8,913.10		\$6,745.69		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Chec
Total									

Section A - Accident Details

Registration Number	SHD6428U
Case Reference Number	TAX/12/24/2092
Registration Date	19/Dec/2017
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	SIM KWANG IMK
Type of Accident	Side Swipe
Accident Date and Time	27/Dec/2024 9:20 AM
Accident Reported Date and Time	27/Dec/2024 2:16 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	ACGJ24120089
Special Instruction to ARC, if any	TP/GREAT AMERICAN
Prepared Date and Time	27/Dec/2024 3:09 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,018.00	\$500.00
Total Spray Cost	\$1,794.00	\$700.00
Total Spare Part Cost	\$6,745.69	\$60.00
Total Other Cost	\$740.00	\$0.00
TOTAL COST	\$10,297.69	\$1,260.00 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Mun San #	MARCUS CHUA (LKK) / Great American
ARC / Surveyor Sign Off Date	31/12/2024 8:45 AM	30/12/2024 6:40 PM
Signature	8W	marcus chua
Remarks	Expected length of repair (days) = 4 days Expected release date of vehicle after repair (Subject to approval from FM and without Supplementary) = 07-01-2025 P/P REPAIR / BEFORE PAINT PHOTO, FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR MARCUS CHUA (LKK) / HP: 9009 6608 / Email: marcuschua@lkkauto.com	

ok. ✓ 9/1/25

[Signature]

Section A - Accident Details

Registration Number	SHD6428U
Case Reference Number	TAX/12/24/2092
Registration Date	19/Dec/2017
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	SIM KWANG IMK
Type of Accident	Side Swipe
Accident Date and Time	27/Dec/2024 9:20 AM
Accident Reported Date and Time	27/Dec/2024 2:16 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	ACGJ24120089
Special Instruction to ARC, if any	TP/GREAT AMERICAN
Prepared Date and Time	27/Dec/2024 3:09 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,018.00	\$500.00
Total Spray Cost	\$1,794.00	\$700.00
Total Spare Part Cost	\$6,745.69	\$543.08
Total Other Cost	\$740.00	\$0.00
TOTAL COST	\$10,297.69	\$1,743.08 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Mun San #	MARCUS CHUA (LKK) / Great American
ARC / Surveyor Sign Off Date	31/12/2024 8:45 AM	30/12/2024 6:40 PM
Signature	SW	Marcus Chua
Remarks	Expected length of repair (days) = 4 days Expected release date of vehicle after repair (Subject to approval from FM and without Supplementary) = 07-01-2025 P/P REPAIR / BEFORE PAINT PHOTO, FOR CHECK ITEM and REPLAGE ITEM PLEASE CALL SURVEYOR MARCUS CHUA (LKK) / HP : 9009 6608 / Email : marcuschua@ikkauto.com	

8/1/25
P/P & 1260

Section C - Quotation and Accident Invoice Details

Quotation Number	E24120172	Invoice Number	
Quotation Date	27/12/2024	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION RH	\$1,018.00	\$500.00
Total Labour	\$1,018.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY REAR DOOR RH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$220.00	\$0.00
TO RESPRAY RIM	\$220.00	\$50.00
TO RESPRAY FILLER RR BUMPER RH	\$220.00	\$50.00
Total Spray Painting & Panel Beating	\$1,794.00	\$700.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$740.00	\$0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		75850479 10	MOULDING ASSY, BODY ROCKER PANEL , RH	0.00	\$649.10	0.00	\$0.00	Replace	Not Given
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$478.90	100.00	\$0.00	Replace	Repair
		52462470 30	PAD, RR BUMPER, RH & LH , 1	0.00	\$4.30	0.00	\$0.00	Replace	Not Given
		52462470 20	PAD, RR BUMPER, RH & LH , 2	0.00	\$4.30	0.00	\$0.00	Replace	Not Given
		52462470 10	PAD, RR BUMPER, RH & LH , 3	0.00	\$4.30	0.00	\$0.00	Replace	Not Given

X
R
X
X
X

Strides Premier Accident Vehicle Repair Estimates

Strides Premier Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 06/01/2025

User ID : PohSuan

	52461470 10	PAD, RR BUMPER, CTR	0.00	\$2.50	0.00	\$0.00	Replace	Not Given	X
	52575470 40	RETAINER, RR BUMPER, RH	0.00	\$127.40	0.00	\$0.00	Replace	Not Given	X
	52161160 10	CLIPS PIECE, FRT BUMPER	0.00	\$4.80	0.00	\$0.00	Replace	Not Given	X
	52453470 10	GUARD, RR BUMPER, LOWER	0.00	\$623.50	0.00	\$0.00	Replace	Not Given	X
	52565479 00	FILLER, RR BUMPER , RH	1.00	\$168.60	100.00	\$0.00	Replace	Repair	R
	81551472 81	LENS & BODY, REAR COMBINATION LAMP , RH	0.00	\$489.00	0.00	\$0.00	Replace	Not Given	X
	81581470 10	LENS & BODY ASSY , RR BUMPER , RH	0.00	\$544.40	0.00	\$0.00	Replace	Not Given	X
	81497470 20	COVER, REAR COMBINATION LAMP, RH	0.00	\$69.90	0.00	\$0.00	Replace	Not Given	X
	67003472 10	PANEL SUB-ASSY, REAR DOOR , RH	1.00	\$1,401.70	100.00	\$0.00	Replace	Repair	R
	68750201 22	HINGE ASSY, REAR DOOR , UPPER RH	0.00	\$107.00	0.00	\$0.00	Replace	Not Given	X
	68770520 31	HINGE ASSY, REAR DOOR , LOWER RH	0.00	\$93.90	0.00	\$0.00	Replace	Not Given	X
	68630470 50	CHECK ASSY, REAR DOOR	0.00	\$199.40	0.00	\$0.00	Replace	Not Given	X
	69211470 21A1	DOOR OUTER HANDLE REAR , RH	0.00	\$105.50	0.00	\$0.00	Replace	Not Given	X
	61601471 50	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$943.10	100.00	\$0.00	Replace	Repair	R
	65637470 60	LINER, REAR FENDER , RH	0.00	\$151.10	0.00	\$0.00	Replace	Not Given	X
	42611474 50	WHEEL, DISC	1.00	\$2,036.30	100.00	\$0.00	Replace	Repair	R
	42450760 20	HUB & BEARING ASSY WITH SPEED SENSOR , REAR	1.00	\$644.10	25.00	\$483.08	Replace	Replace	X
		STICKER LOGO (RR DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	✓
Total				\$8,913.10		\$543.08			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

60
-543.08
+ 500.00
+ 700.00
1,743.08
1260