

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 30561404
Date : 30-12-24
Time of Fax : _____

Via Fax : Email
Your Insured : PBQ 4652-D
Date of Acc : 29-12-24

Attn: Motor Claims Department

Sompo

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH C8246U

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

| | |
|-----------------------------|--|
| ◆ Lim Kwok Eng | Tel: 6214 8355 or HP: 9824 0811 |
| ◆ Jumani Bin Masudin | Tel: 6214 8315 or HP: 9635 5305 |
| ◆ Lim Tien Siong | Tel: 6214 8398 or HP: 9635 8546 |
| ◆ Chiang Liat Choon | Tel: 6214 8314 or HP: 9296 6006 |

} **jumanibm@cdge.com.sg**
Fax no. 6546 8156

→ If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President
Taxi Accident Repair

Date/Time: 30.12.2024 10:05

Page : 1

am: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5965913

JC No305614204

OMER

S COMFORT TRANSPORTATION PTE LTD
OMER NO 7010045
ESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

(R) (O)
(P)

JUNT CARD NO.

REGN NO:

SHC8246U

MILEAGE

MAKE

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

30.12.2024 08:00

DATE/TIME IN

YR OF MANU

08.01.2021

TARGET DATE

CHASSIS CODE


KMHC851CVLU191821

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 29.12.2024
ATURE: 3P.29.12.24

NO LABOR CODE DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

lo.: SHC8246U JU SOMPO

Vehicle No.: SHC8246U

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC8246U

DATE: 30.12.24

MAKE HYUNDAI

MVA JUMANI

MODEL IONIQ

DOA: 29.12.24

SOMPO

| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
|--|-------------------------------|------|------------|-------------------|
| 1 | REAR BUMPER ASSY | | | \$459.40 |
| 1 | REAR BUMPER CENTRE MOULDING | | | \$451.25 |
| 10 | REAR BUMPER CLIPS | | | \$22.00 |
| 1 | REAR BUMPER BEAM | | | \$394.80 |
| 1 | REAR FOG LAMP ASSY | | | \$201.50 |
| 1 | ANTENNA SMARTKEY | | | \$40.50 |
| | SUB TOTAL | | | \$1,569.45 |
| | LESS 25% | | | \$392.35 |
| | DISCOUNTED TOTAL | | | \$1,177.09 |
| | | | | |
| | REVERSE SENSOR | | | \$180.00 |
| | REAR NUMBER PLATE | | | \$55.00 |
| | | | | |
| | LESS 10% | | | |
| | SUB TOTAL NET | | | \$235.00 |
| | | | | |
| | Labour Charge | | | |
| | PANEL BEATING | | | \$400.00 |
| | SPRAY PAINT | | | \$300.00 |
| | REMOVE / REFIX REVERSE SENSOR | | | \$50.00 |
| | | | | |
| | TOTAL LABOUR | | | \$750.00 |
| | | | | |
| | ESTIMATE TOTAL | | | \$2,162.09 |
| | | | | |
| This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. | | | | |