



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL		Ref:	CS/SMO24120457/Uqp3m4 (N)
50 RAFFLES PLACE #03-03		Date:	31/01/2025
SINGAPORE LAND TOWERSINGAPORE 048623		Code:	SMO
ATTN: JIA YI			
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	FBQ 4652D	Veh. Inspected	SHC 8246U
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2404160/JYC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	30/12/2024
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	HYUNDAI AE IONIQ HEV	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	KMHC851CVLU191821	Colour	BLUE
Odometer	227271 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/65R15	DAVANTI	6 mm
L/H Front Tyre	195/65R15	DAVANTI	6 mm
R/H Rear Tyre	195/65R15	DAVANTI	6 mm
L/H Rear Tyre	195/65R15	DAVANTI	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	29/12/2024	Inspection Date	31/12/2024
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD		
	59 LOYANG DRIVE		
	SINGAPORE 508969		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.			
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	