

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/SM02412047/4973

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHC 82464

at Workshop m/s

Combitryn

of

Insured:

FBQ 4052 D

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C 87R

Vehicle: IN / OUT

Date:

Person Contacted:

L7A 19076

Veh No:

SHC 82464 Yr Regn: 08/01/21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

1/1/21 AE IONIQ c.c 15-80

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

227271

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMHCR1 CVLU191821

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Davant

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

29/12/24

D.O.I.

31/12/24

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO SHC8246U
 MAKE HYUNDAI
 MODEL IONIQ

DATE: 30.12.24
 MVA JUMANI
 DOA: 29.12.24

SOMPO

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY		7000	\$459.40
1	REAR BUMPER CENTRE MOULDING		7000	\$451.25
10	REAR BUMPER CLIPS		22	\$22.00
1	REAR BUMPER BEAM			\$394.80
1	REAR FOG LAMP ASSY		11	\$201.50
1	ANTENNA SMARTKEY		11	\$40.50
	SUB TOTAL			\$1,569.45
	LESS 25%			\$392.35
	DISCOUNTED TOTAL			\$1,177.09
	REVERSE SENSOR		mol/fraction	\$180.00
	REAR NUMBER PLATE		scr	\$55.00
	LESS 10%			
	SUB TOTAL NET			\$235.00
	Labour Charge			
	PANEL BEATING		380	\$400.00
	SPRAY PAINT		280	\$300.00
	REMOVE / REFIX REVERSE SENSOR		30	\$50.00
	TOTAL LABOUR			\$750.00
	ESTIMATE TOTAL			\$2,162.09

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hereby
 the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be used
- is subject to final approval from LKK Auto Consultants

Acknowledged by Repairer

Signature:

Date:


am: ARC Repair TP(CLSO)1 JOB CARD Sales Order: 5965913 JC NO305614204

OMER	REGN NO	MILEAGE
S COMFORT TRANSPORTATION PTE LTD	SHC8246U	
OMER NO 7010045	MAKE	FUEL
ESS 383 SIN MING DRIVE	HYUNDAI	E.....1/2.....F
Singapore SINGAPORE 575717	MODEL	DATE/TIME IN
65508755 (R) (O) (P)	IONIQ(G3)	30.12.2024 08:00
	YR OF MANU	TARGET DATE
	08.01.2021	
	CHASSIS CODE	COMPLETION DATE/TIME:
	KMHC851CVLU191821	
JUNT CARD NO.		

Accident Date: 29.12.2024
NATURE: 3P.29.12.24

JOB DESCRIPTION

NO LABOR CODE DESCRIPTION



KED & PASSED OUT BY: _____

SERVICE ADVISOR CUSTOMER'S SIGNATURE

edgement Slip		Exit Pass	
lo.: SHC8246U	JU SOMPO	Vehicle No.:	SHC8246U
Service Advisor	Signature/Date	Name of Service Advisor	Date
turned to Service Reception upon collection		To be kept by Security Guard	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHC8246U
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Dec 2024
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV FL 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	G4LEKU415636
Chassis No.:	KMHC851CVLU191821
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$24,844.00
Original Registration Date:	08 Jan 2021
First Registration Date:	08 Jan 2021
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Jan 2029
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	07 Jan 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$30,510.00
COE Rebate Amount:	\$15,326.00
Total Rebate Amount:	\$19,076.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 31 Dec 2024

OK