



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623 ATTN: GNOH PAU LOONG			Ref: CS/SMO24120460/Uvp3e2(N) Date: 08/01/2025 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 3936U	Veh. Inspected	SMS 9679D
	Policy No.	D24MTHCVE001080	Coverage (\$)	0.00
	Claim No.	CMTD2403656/GPL	Excess (\$)	0.00
	Assign From	GNOH PAU LOONG	Assign Date	12/11/2024
2. Vehicle Particulars & Condition				
	Make & Model	SSANGYONG TIVOLI (A)	c.c	1597
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	KPT30A1USLP319747	Colour	BLACK
	Odometer	190614 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/65 R16	VREDESTEIN	7 mm
	L/H Front Tyre	205/65 R16	VREDESTEIN	7 mm
	R/H Rear Tyre	205/65 R16	VREDESTEIN	7 mm
	L/H Rear Tyre	205/65 R16	VREDESTEIN	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/11/2024	Inspection Date	13/11/2024
	Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	