REF: CS/INC24120463/Avh3

Assist. Surv:

ASSIGNMENT

From: Date:

Estim. Cost:

OD / TP RES / CD RES / EVA / INV / MV

To Inspect Vehicle No:

at W/Shop/Workshop

of

Insured: SNP 5340K

Policy No:

Claim's No: MT/1310451-002

Sum Insured: Excess:

(Client Record)

Make of Veh:

(Policy Condition)

Remark: Veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Scan: Consistent? : Yes or No

Est. Repair: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SNG2750C Yr Regn: 2022, July.

Type: M.Car / M.Cycle / Bus / Van / Lorr / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Stepwagon O.D. 1993

Colour: White A/C: Insured / Std / NI / NA

Sp.Reading: 339485 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RP51220584

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LEA / MIC / OHTSU / PIR / SUMI / TOYO / YORO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.	28/12/2024	D.O.I.	31/12/24

Survey held at Rydes.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Front N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP / NC
21/2/25	Adrian confirmed LS $4500 (Red 6352.48, 58%)
	MV :
	PV :
	Nett :

COE Expiry :

Estimate given during 1st Survey : Yes (✓) No ( )

4672

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Days Of Repair: 5

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Inve ($)

Survey Fee:

Transportation: S + R$ S

Photos

Others