

Veron

ESTIMATE OF REPAIR

Veh# : SNG2750C

Model: Honda stepwagon

Accident Date

Location

3P: SNP5340K NTUC

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front headlamp Lh <i>ut</i>	2,970.40	✓	
2	1 pc	Front headlamp lower bracket <i>pcu</i>	169.80	+	
3	1 pc	Front grille <i>2</i>	1,400.50	+	
4	1 pc	Front grille Logo <i>pcu</i>	91.80	+	
5	1 set	Front grille clip		100.00	+
6	1 pc	Front bumper <i>Dehnd</i>	1550.60	1185	
7	1 pc	Front bumper middle bracket lower (INNER) <i>pcu</i>	310.20	+	
8	1 pc	Front bumper chrome lower Lh <i>pcu</i>	110.00	+	
9	1 pc	Front bumper reinforcement <i>pcu</i>	456.50	+	
10	1 pc	Front bumper fog lamp Lh <i>pcu</i>	292.00	+	
11	1 pc	Front bumper fog lamp cover LH <i>pcu</i>	101.80	+	
12	2 pcs	Front bumper side retainer R/L <i>pcu</i>	292.20	+	
13	1 set	Front bumper clip <i>pcu</i>		50.00	30
14	2pcs	Front sensor <i>pcu</i>	610.00	+	
15	1 pc	Front fender Lh <i>Dented</i>	885.00	✓	
16	1 pc	Front fender inner shield LH <i>Dehnd</i>	256.80	✓	
17	1 sets	Front fender inner shield clip R/L <i>pcu</i>		60.00	30

5297.20

S.N: 60

4237.76

18	1 pc	Front fender side bracket panel LH <i>new</i>	530.50	+	
		Sub-Total:	10,028.10	210.00	0.00
			20%	0%	10%
		After Less %:	8,022.48	210.00	0.00
		Labour			
1		To remove & refix accident damaged parts & realign affected area.	1,200.00	600	
2		To spray paint on accident affected area.	1,000.00	700	
3		To check wiring and head lamp focus	120.00	30	
4		To diagnosis & reset after work.	300.00	+	
		Sub-Total:	2,620.00		
		Total:	10,852.48		
		after less 20%:	8,681.98		

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)

Adrian Lj
2/5 31/12/24

05 Days



8778 1999
24 hr accident call



total: 5627.76

L/S: 4.5k

4.5k

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: