

ASS. REC. BY: **Steve**

REF: CS/FCI24120472/Evp3

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: **SHD 3420K**

Policy No. \_\_\_\_\_


Claims No. **D25000131MFCT**

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: **SNP4908E** Yr Regn: **21 Feb 2024**Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: **HONDA STEPWAGON SPADA** c.c. **1993**Colour: **White** A/C: Insured / Std / NI / NASp. Reading: **66345** T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: **RP81039302** \*Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_Tyre Size: F: **205/60R16**R: **"**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. **6** mm R/Bal. **6** mmL/Bal. **6** mm L/Bal. **6** mmD.O.A. **27/12/24** D.O.I. **14/01/25**Survey held at **Jack Cars**Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<b>MV - \$180k</b>
17/1/25	Steve confirmed final fig \$890 (red 1260, 58%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: \_\_\_\_\_

Lump Sum / L.B.I. (\$) \_\_\_\_\_

Days Of Repair: **2**

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. SI

Photos

Others

TOTAL