



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24070047/Kvh3e2
(BUDGET DIRECT INSURANCE)	Date:	22/07/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKT 4496R	Veh. Inspected	SFC 9600Y
Policy No.	P10183704R05	Coverage	0
Claim No.	C10030317/KR	Excess	\$0.00
Assign From	FRAULEINE KHOO	Assign Date	02/07/2024

### 2. Vehicle Details

Make & Model	TESLA MODEL Y (A)	C.C	-
Engine No.	-	Year of Reg.	04/05/2023
Chassis No.	LRWYHCFS6PC892718	Colour	METALLIC GREY
Odometer	26548 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	255/45 R19	HANKOOK	7
L/H Front Tyre	255/45 R19	HANKOOK	7
R/H Rear Tyre	255/45 R19	HANKOOK	7
L/H Rear Tyre	255/45 R19	HANKOOK	7

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	01/07/2024	Inspection Date	04/07/2024
Survey held at	OPTIMA WERKZ PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days