

ASS. REC. BY:

REF:

AGW CS/AGI24070047/Kvh3

C

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

SKT 4496R

Policy No.

Claims No. C10030317/KR

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

100m

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SFC 96004

Yr Regn:

05, 23

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Tesla Model Y

c.c

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

26548

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

LRWYHCF S6PC 892718

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

255/45R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

1 Hankook

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

1/7/24

D.O.I.

4/7/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/7 8:57:14.92 Calw (red 1537.56, 21%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: 4

Resurvey No. of Trlp:

Survey Fee:

Transportation

S - RS - SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	358Z
Vehicle Details	
Vehicle No.:	SFC9600Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	02 Jul 2024
Vehicle Make:	TESLA
Vehicle Model:	MODEL Y RWD
Primary Colour:	Grey
Manufacturing Year:	2023
Engine No.:	-
Chassis No.:	LRWYHCF56PC892718
Maximum Power Output:	220.0 kW (295 bhp)
Open Market Value:	\$61,318.00
Original Registration Date:	04 May 2023
First Registration Date:	04 May 2023
Transfer Count:	0
Actual ARF Paid:	\$44,295.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 May 2033
PARF Rebate Amount:	\$33,221.00
Intended COE Rebate Details	
COE Expiry Date:	03 May 2033
COE Category:	B - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$120,889.00
COE Rebate Amount:	\$96,711.00
Total Rebate Amount:	\$129,932.00
Message	

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.  
The information contained herein is correct as at 02 Jul 2024

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of First Submission	02/07/2024 10:00 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	01/07/2024 17:30 (SGT)
Exact Location of Accident	Near 11 Jalan Anak Bukit, Singapore
Additional Location Information	ON ANAK BUKIT FLYOVER
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFC9600Y
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	TEO HONG WEE
NRIC No	SXXXX358Z
Email Address	NTEOHW@HOTMAIL.SG
Mobile Phone No	(Phone) +65-93629732
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	Tesla
Model	MODEL Y
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1999

### INSURANCE COMPANY

Name of Insurance Company	ECICS Limited
Policy Number / Cover Note Number	MPC24A00135100

### DRIVER

Name of Driver	TEO HONG WEE
NRIC No	SXXXX358Z
Date Of Birth	10/05/1971
Occupation	Indoor

Driving Pass Date	24/11/1994
Driving experience	29 YEARS AND 8 MONTHS
Gender	Male
Mobile Number	(Phone) +65-93629732
Alt. Phone Number	-
Email Address	NTEOHW@HOTMAIL.SG
Address	583 WOODLANDS DRIVE 16
Address complement	#11-460
Postcode	S730583
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO SKETCH PLAN

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKT4496R
Vehicle Manufacturer	Toyota
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	SHI
Contact Number	(Phone) +65-93385172

Address -  
Address complement -  
Postcode -  
Insurance Company Name -  
Nature Of Damage -  
Details of property damaged in accident -  
No. Of Passenger (Including Driver) -

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

bbsh.

02 Jul 24

0855hrs

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Anak Bukit Timah

Flyover



Veh A: SFC9600Y

Veh B: SKT4496R







# INVOICE

**BILL TO :**


Name : Nelson Teo  
Contact Number : 9362 9732

DATE : 5 June 2024

INVOICE : INV02598

Vehicle Make/Model/Colour : Tesla / Model 3 /White  
Vehicle Registration Number : SKV 1332 P

Payment Mode : CASH / BANK/TT

DESCRIPTION	AMOUNT
<b>Magnus Pro Optimum Paint Protection Film</b> Full Exterior Gloss PPF package Centre Console PPF (FOC) <b>Magnus Pro Nano-Ceramic Window Film Package</b> N.A  <b>Nanonix Ceramic Coating</b> N.A	\$ 4,980.00
Discount Booking Deposit Paid :	
 SCAN TO PAY	
<b>Magnus PRO Warranty :MP20240605250 Nanonix Warranty :</b>  <b>Magnus Pro Paint Protection Film (PPF) Warranty</b> 6 Years* against Bubbles, Cracking, and Delaminating  *This warranty does not extend coverage to damage caused by normal wear and tear, environmental damages, road debris impact, accidents, collisions or intentional damage of any kind.	
<b>Amount PAID :</b>	<b>\$ 4,980.00</b>

GK Detailing Pte Ltd | 25 Kaki Bukit Rd 4, #06-59, Synergy @ Kaki Bukit, Singapore 417800  
T: +65 9155 1806 / +65 9658 8936 | E: info@ace-gk.com





Vehicle Make/Model/Colour : Tesla / Model Y / Grey  
Vehicle Registration Number : SFC 9600 Y

Date: 02/07/2024

Vehicle No: SFC9600Y

Model: TESLA MODEL Y RWD

Chassis: LRWYHCF56PC892718-2023

Reg.Year: 2023

Third Party Insurer: AGI

Third Party Veh No: SKT4496R

Date of Accident: 01/07/2024

Estimator: TING AN

Surveyor:

*Not Authorised  
Penny B4 pain  
4 days  
85714.92*

## ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAILGATE	1		<i>Ry</i> \$1,219.62 ✓
2	REAR TAILGATE "TESLA" EMBLEM	1		<i>m</i> \$48.59 ✓
3	REAR TAILGATE INNER TRIM BOARD	1		<i>Pm</i> \$116.82 X
4	REAR BUMPER	1		<i>Bm</i> \$836.45 ✓
5	REAR BUMPER LOWER LIP	1		<i>nd / Gt</i> \$542.05 ✓
6	REAR BUMPER LOWER LIP CENTER COVER	1		<i>Sm</i> \$20.56 X
7	REAR BUMPER REFLECTOR LH	1		<i>cm</i> \$40.18 ✓
8	REAR BUMPER SIDE BRACKET LH	1		<i>R</i> \$5.60 X
9	REAR BUMPER REINFORCEMENT	1		<i>Ry</i> \$299.06 ✓
10	REAR BUMPER CENTER BRACKET	1		<i>cm</i> \$8.41 ✓
11	REAR BUMPER PARKING SENSOR	1		<i>Sm</i> \$158.87 X
12	REAR BUMPER PARKING SENSOR BRACKET	1		<i>R</i> \$6.54 X
13	REAR END PANEL	1		REPAIR
SUB TOTAL				\$3,302.75
LESS 10%				-\$330.28
PARTS TOTAL				\$2,972.48

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		\$100.00 <i>4050</i>
2	REAR TAILGATE INNER TRIM BOARD CLIPS	1		<i>m</i> \$50.00 ✓
3	REAR BUMPER CLIPS	1		<i>m</i> \$50.00 ✓
4	PPF FOR AFFECTED AREAS	1	<i>(Bill)</i>	\$1,850.00 <i>1750</i>
S/N TOTAL				\$2,050.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 Fax: (+65) 6481 1011



Date: 02/07/2024  
Vehicle No: SFC9600Y  
Model: TESLA MODEL Y RWD  
Chassis: LRWYHCFS6PC892718-2023  
Reg.Year: 2023

Third Party Insurer: AGI  
Third Party Veh No: SKT4496R  
Date of Accident: 01/07/2024  
Estimator: TING AN  
Surveyor:

**LABOUR CHARGES:**

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.	\$700.00	400/
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE, REAR BUMPER, REAR END PANEL & ETC.	\$700.00	440/
LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOULDING, REAR WINDSCREEN SEALANT & ETC.	\$150.00	120/
LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.	\$120.00	60/
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER PARKING SENSOR & ETC.	\$120.00	60/
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$120.00	30/
TO DIAGNOSIS FAULT CODE & RESET MEMORY.	\$200.00	nn X
TO CHECK WIRING & ELECTRICAL SYSTEM.	\$120.00	20/

LABOUR TOTAL	\$2,230.00
--------------	------------

TING AN	TOTAL	\$7,252.48
---------	-------	------------

**Head office**

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

**Branch**

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

**Branch (Motor Insurance Claims)**

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

