



3rd party was driving on the 3rd lane(going straight only) from the left while OI bus was on the left side of 3rd party. OI's lane can turn left and go straight.





While crossing junction, OI should keep to left as per road marking.







From video, 3rd party was driving within his lane and there is a jerk on his car while crossing the junction.

