



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24070051/Anh3m4
(BUDGET DIRECT INSURANCE)	Date:	26/12/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJV 4397U	Veh. Inspected	SNP 6141L
Policy No.	P11030396R00	Coverage	0
Claim No.	C10030236/ML	Excess	\$0.00
Assign From	MICHAEL	Assign Date	02/07/2024

2. Vehicle Details

Make & Model	HONDA CITY	C.C	1497
Engine No.	L15Z11422124	Year of Reg.	22/01/2015
Chassis No.	MRHGM6660EP000247	Colour	SILVER
Odometer	148827 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/55R16	YOKOHAMA	6
L/H Front Tyre	185/55R16	YOKOHAMA	6
R/H Rear Tyre	185/55R16	YOKOHAMA	6
L/H Rear Tyre	185/55R16	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/06/2024	Inspection Date	08/07/2024
Survey held at	ADVANCE AUTO GARAGE 23 KAKI BUKIT AVENUE 4, #04-01 VICOM KAKI BUKIT INSPECTION CENTER, SINGAPORE 415933.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days