

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	MS FIRST CAPITAL INSURANCE LTD		Ref:	CS/FCI24070054/Avp3	
	16 RAFFLES QUAY #42-01 HONG LEONG BUILDING		Date:	02/07/2024	
	#42-01 HONG LEOF SINGAPORE 04858		Code:	FCI2	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SH 6761E	Veh. Inspected	SMX 4578T	
	Policy No.	D-24101861MFCT	Coverage	0	
	Claim No.	D24005710MFCT	Excess	\$0.00	
	Assign From	BETTY	Assign Date	02/07/2024	
2. Vehicle Details					
	Make & Model	MAZDA 6	c.c	1998	
	Engine No.	PE20718134	Year of Reg.	26/02/2016	
	Chassis No.	JM6GJ1072G0226231	Colour	WHITE	
	Odometer	113637 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3.	3. Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	225/55 R17	LASSA	6	
	L/H Front Tyre	225/55 R17	LASSA	6	
	R/H Rear Tyre	225/55 R17	LASSA	6	
	L/H Rear Tyre	225/55 R17	LASSA	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	28/06/2024	Inspection Date	03/07/2024 (13:28)	
	Survey held at	rvey held at HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a. Remarks					
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
-1.	5b. Estimate Days of Repair				

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days