



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref:	CS/SMO24070061/Anp3m4 (N)
50 RAFFLES PLACE #03-03			Date:	27/01/2025
SINGAPORE LAND TOWERSINGAPORE 048623			Code:	SMO
ATTN: PAU LOONG				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 8768X	Veh. Inspected	SNC 1642J	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2402167/GPL	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	02/07/2024	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NOTE	c.c	1198	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	JN1FAAE13Z0900015	Colour	BLUE	
Odometer	99065 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60R16	YOKOHAMA	6 mm	
L/H Front Tyre	185/60R16	YOKOHAMA	6 mm	
R/H Rear Tyre	185/60R16	YOKOHAMA	6 mm	
L/H Rear Tyre	185/60R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/07/2024	Inspection Date	02/07/2024	
Survey held at	TSL AUTO PRO SELECTION PTE LTD BLK 1 KAKI BUKIT AVENUE 6 #01-06 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	