

REF: CS/CTI24070070/Avp3

ASSIGNMENT

From: _____ Date: _____

Estim: _____

OD / ~~TP~~ / TP RES / CD RES / EVA / INV / MVTo in ~~Vehicle~~ No: _____at ~~W/O~~ ~~Est~~ / m/s _____

of _____

Insured: **SNE 8074S**

Policy No: _____

Claims No: **SNM24D203622**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: Tlveh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SLZ5330K** Yr Regn: **2018 May**Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: **Mazda 3** CO: **1496**Colour: **Blue** A/C: Insured / Std / NI / NASp. Reading: **139083** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **Jm6BN22A8H0169121**Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModif: Nil / S/Rim / STD A/Rim orTyre Size: F: **205/60R16**R: **205/60R16**BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. **06** mm R/Bal. **06** mmL/Bal. **06** mm L/Bal. **06** mmD.O.A. **22/6/2024** D.O.I. **09/07/24**Survey held at **Modern**Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

13/8/24 **TP Chinc** **COE Expiry**
Adrian confirmed LS \$1600 (red 6721.28, 80%)MV: **581K**PV: **24.2K**Nett: **33.8K**

Estimate given during: Yes ()

1st Survey: No (✓)

5862

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: **2**

1) _____

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

Transportation:

2) _____

3 + RS. \$1

Photos

Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Inve (\$)

Report Format:

Report Form: A/P 1/1