



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24070071/Uvp3
16 RAFFLES QUAY	Date:	30/07/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 415L	Veh. Inspected	SFX 3339G
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24005784MFCT	Excess	\$0.00
Assign From	-	Assign Date	03/07/2024

2. Vehicle Details

Make & Model	B.M.W. 420I GRAN COUPE (A)	C.C	1998
Engine No.	H3013378B48B20A	Year of Reg.	14/08/2019
Chassis No.	WBA4H32060BX80273	Colour	GREY/BLACK
Odometer	91806 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	MICHELIN	245/35ZR19	6
L/H Front Tyre	MICHELIN	245/35ZR19	6
R/H Rear Tyre	MICHELIN	275/30ZR19	6
L/H Rear Tyre	MICHELIN	275/30ZR19	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/07/2024	Inspection Date	03/07/2014
Survey held at	ZOOM AUTOWERKS PTE LTD - BLK 15 KAKI BUKIT ROAD 4, BARTLEY BIZ CENTRE, #01-53 SINGAPORE 417808		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days