

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0463/2024/EQ  
DATE : 11-Jun-24  
WIP : 19110

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/6/2024

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR MATHUR ANURAG CHANDRA  
ADDRESS : WATERSIDE, BLOCK 3  
#04-04  
SINGAPORE 436881  
TELEPHONE : HP +65 98247729  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 1800075916-06  
VEHICLE NO : SMC 1230 B  
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC  
MODEL YEAR : 26/6/2018  
ENGINE NO : CZD 870549  
CHASSIS NO : WAUZZZ8U7JR070338  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 7-Jun-24  
PLACE OF ACCIDENT : ENTRANCE OF FORT ROAD FROM ECP



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMC 1230 B**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER.	S/N \$	360.00	/
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,600.00	500
4	TO RESPRAY FRONT BUMPER.	\$	1,200.00	550
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	/
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$</b>	<b>3,852.00</b>

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 1230 B**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Y P</i>	1	\$	2,544.00
2	FRONT BUMPER FIXING PARTS <i>X</i>	1	\$	122.00
3	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>X</i>	2	\$	384.00
4	FRONT BUMPER GRILLE - CENTER <i>X</i>	1	\$	272.00
5	FRONT BUMPER CLOSING ELEMENT - LOWER <i>X</i>	1	\$	221.00
6	FRONT BUMPER SPOILER <i>X</i>	1	\$	479.00
7	RADIATOR GRILLE <i>OR</i>	1	\$	1,421.00
8	RADIATOR GRILLE STRIKER PLATE <i>?</i>	1	\$	163.00
9	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	1	\$	129.00
10	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>?</i>	1	\$	1,116.00
11	FRONT BUMPER REINFORCEMENT BEAM COVER <i>?</i>	1	\$	82.00
12	OUTSIDE TEMPERATURE SENSOR BRACKET <i>Y</i>	1	\$	30.00
13	FRONT WHEEL COVER - LH / RH <i>OR</i>	2	\$	612.00
14	HEADLIGHT - RH <i>X</i>	1	\$	9,325.00
15	HEADLIGHT RETAINING PLATE - RH <i>X</i>	1	\$	109.00
16	LIFT CYLINDER - RH <i>X</i>	1	\$	167.00
17	LIFT CYLINDER HOSE <i>X</i>	1	\$	233.00
18	HEADLIGHT MOUNTING - RH <i>X</i>	1	\$	147.00
19	HEADLIGHT SUPPORT - RH <i>X</i>	1	\$	32.00
20	FRONT NUMBER PLATE <i>OR</i>	S/N	\$	60.00
21	SUNDRIES <i>?</i>		\$	500.00
TOTAL SPARE PARTS		:	\$	18,148.00
TOTAL LABOUR CHARGES		:	\$	3,852.00
GRAND TOTAL		:	\$	22,000.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :  
SURVEYED DATE :  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS :

Steve (CLKK)  
14/6/24, 10.30am  
OD - Not AL  
Exp - ?  
P/P

My B/L M, 3 days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT





## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of First Submission	10/06/2024 16:45 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	07/06/2024 17:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ENTRANCE OF FORT RD FROM ECP
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMC1230B
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	MATHUR ANURAG CHANDRA
Passport No/FIN	GXXXX945Q
Email Address	SHIPLINK@REDIFFMAIL.COM
Mobile Phone No	(Phone) +65-98247729
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Audi
Model	Q3
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1400

#### INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	1800075916-06

#### DRIVER

Name of Driver	MATHUR ANURAG CHANDRA
Passport No/FIN	GXXXX945Q
Date Of Birth	02/04/1962
Occupation	Indoor

Driving Pass Date	27/12/2012
Driving experience	11 YEARS AND 6 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98247729
Alt. Phone Number	-
Email Address	SHIPLINK@REDIFFMAIL.COM
Address	WATERSIDE, BLOCK 3
Address complement	#04-04
Postcode	436881
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO THE SKETCH PLAN AND ACCIDENT STATEMENT.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH9999A
Vehicle Manufacturer	Audi
Vehicle Model	Q5
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-

Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
10 JUNE 14  
1300 HRS  
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel

### Sketch Plan





## Describe Circumstances of the Accident

ON 07TH JUNE, AROUND 1730 HRS, WHILE RETURNING FROM OFFICE. AS I TURNED INTO FORT ROAD WHILE COMING FROM MCE TUNNEL, THE CAR IN FRONT OF ME SUDDENLY SLOWED DOWN / STOPPED, AND EVEN THOUGH I ~~APPLIED~~ APPLIED MY BRAKES IMMEDIATELY, MY CAR AUDI Q3 NO. 9ME 1230R TOUCHED THE LEFT SIDE ON REAR OF THE OTHER CAR LIGHTLY. THE OTHER CAR WAS AUDI Q5, NUMBER CLH 9999A AND WAS DRIVEN BY MR. NAIN N GURNANI NRIC NO. S 8561392-H.

THERE WAS NO INJURY TO ME OR TO THE OTHER DRIVER MR. NAIN N GURNANI.


\*  
AND BUMPER  
SCRATCH  
MARKS

THE ~~DA~~ APPARENT DAMAGE TO Q5 WAS TO ITS REAR LEFT SIDE LIGHT. I DID NOT NOTICE ANY OTHER SCRATCH OR DAMAGE, BUT THEY MAY BE THERE!

THE DAMAGE TO Q3 (MY CAR) WAS THAT THE FRONT RIGHT BUMPER WAS SLIGHTLY COMING OUT OF ITS ALIGNMENT, THERE IS SCRATCH SLIGHTLY TO THE FRONT RADIATOR GRILL (MINOR) BUMPER CAP WHICH WAS SLIGHTLY DISLOIDGED ON THE RIGHT SIDE WAS FIXED BY PUSHING IN.

## Declaration

I/We declare the foregoing particulars are true in every respect

  
10 JUNE 24  
1300 HRS  
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre  
Personnel