



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24070082/Kvp3m4
(BUDGET DIRECT INSURANCE)	Date:	12/09/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMG 4941S	Veh. Inspected	SFE 8778P
Policy No.	-	Coverage	0
Claim No.	C10030309/HY	Excess	\$0.00
Assign From	HUI YEN	Assign Date	03/07/2024

2. Vehicle Details

Make & Model	VOLKSWAGEN TOURAN 1.4 TSI (A)	C.C	1395
Engine No.	CZD281710	Year of Reg.	17/04/2017
Chassis No.	WVGZZZ1TZW074634	Colour	METALLIC GREY
Odometer	143744 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/55R17	PIRELLI	8
L/H Front Tyre	215/55R17	PIRELLI	8
R/H Rear Tyre	215/55R17	PIRELLI	6
L/H Rear Tyre	215/55R17	PIRELLI	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/07/2024	Inspection Date	03/07/2024
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days