



BLUWEL AUTOMOTIVE SERVICE PTE LTD
1 MAN BUAT AVE 6 AUTOBAY #01-201/202 SINGAPORE 477065
TEL: 8740288 FAX: 88413988 EMAIL: info@bluwel.com.sg

CUSTOMER'S VEHICLE NO.: SKW 6975X DATE OF ACCIDENT: 18/03/2024
3RD PARTY INSURANCE COMPANY: Lifeline


This is to confirm that:



-1 a) NAME OF APPOINTED SURVEYOR: Koharyon HP: 9245 2652
b) NAME OF SURVEYOR'S COMPANY/ COMPANY'S STAMP & SIGNATURE 145 Prox



has completed the **PRE-REPAIR SURVEY ON:** 18/03/2024 TIME: 8:05U
Remark: To arrange with us 1 working day in advance


-2 a) NAME OF APPOINTED SURVEYOR: As above/ HP: _____
b) NAME OF SURVEYOR'S COMPANY/ COMPANY'S STAMP & SIGNATURE: _____

has completed the **DISMANTLE PARTS SURVEY ON:** _____ TIME: _____
Remark: _____























Stamford Tyres International Pte Ltd

#01-12/13 Syntropy@KB

Singapore 477801


Phone Number: 6702 3355

Fax Number: 6341 6993

Customer:	Date:	3/13/2024 3:40 PM
Company:	VIN	
License NO:	Technician:	
Odometer:	Order NO:	
SKW6875X		
361678KM		

VEHICLE ALIGNMENT REPORT
TOYOTA COROLLA ALTIS 13-13 (Customized)

Primary Angles		Specifications		Initial	Final
		Min	Max		
Front	Caster	Left	4°10'	5°40'	---
	Camber	Right	4°10'	5°40'	---
		Left	1°48'	0°55'	1°48'
	Toe	Right	-1°00'	0°35'	-1°00'
		Left	-2°48'	0°00'	2°48'
Rear	Camber	Right	-1°48'	0°08'	-1°48'
		Left	1°00'	0°17'	1°00'
	Toe	Right	-1°12'	-0°25'	-1°12'
		Left	-1°18'	-0°25'	-1°18'
	Total	Right	0°00'	0°17'	0°15'
Max Thrust Angle		Left	0°00'	0°17'	0°09'
		Total	0°24'	0°34'	0°24'
		Min	---	---	-0°03'
Secondary Angles		Specifications		Initial	Final
		Min	Max		
SAI	Left	11°20'	11°20'	---	---
	Right	11°20'	11°20'	---	---
Included Angle	Left	---	---	---	---
	Right	---	---	---	---



BLUWEL AUTOMOTIVE SERVICE PTE LTD
 1 KAM BUKIT AVE & AUTOBAY #01-28/30/33/35 SINGAPORE 417883
 TEL: 67420888 FAX: 98412088 E-MAIL: info@bluwel.com.sg

CUSTOMER'S VEHICLE NO. SKW6975X DATE OF ACCIDENT: 14/05/2024
 3RD PARTY INSURANCE COMPANY: Liberty


This is to confirm that:

- 1 a) NAME OF APPOINTED SURVEYOR: Khalidudin HP: 93451650
 b) NAME OF SURVEYOR'S COMPANY/ COMPANY'S STAMP & SIGNATURE

has completed the PRE-REPAIR SURVEY ON: 14/05/2024 TIME: 11:00
Remark: To arrange with us working day is ok

- 2 a) NAME OF APPOINTED SURVEYOR: As above/ Khalidudin HP: 93451650
 b) NAME OF SURVEYOR'S COMPANY/ COMPANY'S STAMP & SIGNATURE

has completed the DISMANTLE PARTS SURVEY ON: 14/05/2024 TIME: 16:00
Remark:











BLUWEL AUTOMOTIVE SERVICE PTE LTD
110, BLUWEL AVE, AUTOMOTIVE SERVICES, SINGAPORE 610180
TEL: 6750 0740 FAX: 6741 0006 E-MAIL: info@bluwel.com.sg

CUSTOMER'S VEHICLE NO. SKW6975X DATE OF ACCIDENT 10/05/2016
3RD PARTY INSURANCE COMPANY Liberty

This is to confirm that:

-1- a) NAME OF APPOINTED SURVEYOR: Edgardo HP: 144 1964
b) NAME OF SURVEYOR'S COMPANY: LIBERTY HP: 144 1964
has completed the **PRE-REPAIR SURVEY ON** 10/05/2016 TIME: 22:50
Remark: To straighten up the hood

-2- a) NAME OF APPOINTED SURVEYOR: As above Edgardo HP: 144 1964
b) NAME OF SURVEYOR'S COMPANY: LIBERTY HP: 144 1964
has completed the **DISMANTLE PARTS SURVEY ON** 10/05/2016 TIME: 01:00
Remark:

-3- a) NAME OF APPOINTED SURVEYOR: As above Edgardo HP: 144 1964
b) NAME OF SURVEYOR'S COMPANY: LIBERTY HP: 144 1964
has completed the **AFTER REPAIR SURVEY ON** 10/05/2016 TIME: 01:00

pursuant to the State Courts Practice Direction (Amendment No. 1 of 2016)

