

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internat	tionale Des Experts En	Automobile
ИS	MS FIRST CAPITA	L INSURANCE LTD	Ref:	CS/FCI24070091/Knp3m4
	16 RAFFLES QUA		Date:	24/09/2024
	#42-01 HONG LEC SINGAPORE 0485		Code:	FCI2
1.		Policy Particular	s :- THIRD PARTY CLA	JM
	Insured Veh.	SHA 6015T	Veh. Inspected	SNH 843B
	Policy No.	D-24101861MFCT	Coverage	0
	Claim No.	D24005778MFCT	Excess	\$0.00
	Assign From	BETTY	Assign Date	03/07/2024
2.		Veh	nicle Details	
	Make & Model	NISSAN SERENA (A)	c.c	1198
	Engine No.	HR12297606K	Year of Reg.	26/09/2022
	Chassis No.	JN1EBAC27Z0001373	Colour	METALLIC PEARL WHITE
	Odometer	48077 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: STANDARD ALLOY RIM		
3.		Cond	itions of Tyres	
		Size	Make	Balance (mm)
	R/H Front Tyre	205/60R16	ZEXTOUR	8
	L/H Front Tyre	205/60R16	ZEXTOUR	8
	R/H Rear Tyre	205/60R16	DAVANTI	8
	L/H Rear Tyre	205/60R16	DAVANTI	8
4.		Descrip	tion of Damages	
ΉE	VEHICLE SUSTAIN	NED DAMAGES AT THE REAR O/S	PORTION.	
	AGES SEE DETAIL	_S.		
)AN	5. General Information			
		Gener	ral Information	
5.	Accident Date	30/06/2024	ral Information Inspection Date	04/07/2024
5.	Accident Date Survey held at		Inspection Date	04/07/2024
5.		30/06/2024  COMFORTDELGRO ENGINEER 205 BRADDELL ROAD BLK C, 3RD FLOOR SINGAPORE 579701.	Inspection Date	04/07/2024
<b>5</b> a. A)D <i>A</i>	Survey held at  AMAGES CONSIST HE INSPECTION WA	30/06/2024  COMFORTDELGRO ENGINEER 205 BRADDELL ROAD BLK C, 3RD FLOOR SINGAPORE 579701.	Inspection Date ING PTE LTD  Remarks  PREJUDICE" BASIS.	

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days