

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrotauto.com

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **SNJ 412B**
Made : Toyota
Model : Lexus ES250
Chassis No : JTHB11B1602002887

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Bonnet ✓ nn	1	\$ 1,838.40	\$ 1,838.40
2	Front Bonnet Hinge RH ✗ nn	1	\$ 101.20	\$ 101.20
3	Front Bonnet Hinge LH ✗ nn	1	\$ 101.20	\$ 81.20
4	Front Bonnet Lock ✗ nn	1	\$ 170.10	\$ 170.10
5	Front Bumper ✗ R	1	\$ 1,557.50	\$ 1,557.50
6	Front Bumper Number Plate Garnish ✗ nn	1	\$ 141.60	\$ 141.60
7	Front Bumper Side Retainer RH ✗ nn	1	\$ 103.90	\$ 103.90
8	Front Bumper Side Retainer LH ✗ nn	1	\$ 103.90	\$ 103.90
9	Front Bumper Inner Sponge ✗ nn	1	\$ 152.50	\$ 152.50
10	Front Bumper Reinforcement ✗ nn	1	\$ 1,359.70	\$ 1,359.70
11	Front Bumper Tow Cover RH ✗ nn	1	\$ 73.10	\$ 73.10
12	Front Bumper Tow Cover LH ✗ nn	1	\$ 73.10	\$ 73.10
13	Front Bumper Fog Lamp Garnish RH ✗ nn	1	\$ 302.80	\$ 302.80
14	Front Bumper Fog Lamp Garnish LH ✗ nn	1	\$ 302.80	\$ 302.80
15	Front Bumper Bracket RH ✗ nn	1	\$ 161.10	\$ 161.10
16	Front Bumper Bracket LH ✗ nn	1	\$ 161.10	\$ 161.10
17	Front Grille Assembly ✗ nn	1	\$ 2,262.60	\$ 2,262.60
18	Front Grille Emblem ✗ nn	1	\$ 1,177.60	\$ 1,177.60
19	Front Headlamp Assembly RH / Rep scratched	1	\$ 6,191.60	\$ 6,191.60 /
20	Front Headlamp Assembly LH ✗ nn	1	\$ 6,191.60	\$ 6,191.60
21	Front Support Panel ✗ nn	1	\$ 1,924.00	\$ 1,924.00
22	Front Support Panel Top Garnish ✗ nn	1	\$ 247.50	\$ 247.50
23	Aircon Condenser ✗ nn	1	\$ 2,726.00	\$ 2,726.00
24	Radiator ✗ nn	1	\$ 3,148.80	\$ 3,148.80
25	Front Fender RH / DD	1	\$ 2,416.50	\$ 2,416.50 /
26	Front Fender Inner Shield RH ✗ nn	1	\$ 717.00	\$ 717.00
27	Front Wheel Rim RH / Repair cost - cut	1	\$ 4,268.20	\$ 200 / 4,268.20
28	Front Shock Absorber RH ✗ nn	1	\$ 1,013.30	\$ 1,013.30
29	Front Lower Arm RH ✗ nn	1	\$ 1,140.40	\$ 1,140.40
30	Front Knuckle Arm RH ✗ nn	1	\$ 1,002.50	\$ 1,002.50
31	Front Wheel Bearing RH ✗ nn	1	\$ 830.20	\$ 830.20
32	Front Door Side Mirror Assembly RH / BR	1	\$ 2,150.40	\$ 2,150.40 /
33	Front Door Assembly RH / BR	1	\$ 3,043.80	\$ 3,043.80 /

(Video take cannot flip)

13,802.30
-10%
12,422.07

Parts Sub Total :	\$	47,136.00
10% Discount	\$	4,713.60
PARTS TOTAL :	\$	42,422.40

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Number Plate X nn	1	\$ 50.00	\$ 50.00
2	Front Bumper Clips - Set X nn	1	\$ 50.00	\$ 50.00
3	Front Grille Assembly Clips - Set X nn	1	\$ 50.00	\$ 50.00
4	Front Headlamp Clips - Set X nn	1	\$ 50.00	\$ 50.00
5	Front Support Panel Top Garnish Clips - Set X nn	1	\$ 30.00	\$ 30.00
6	Front Fender Inner Shield Clips - Set X nn	1	\$ 50.00	\$ 50.00
7	Front Door Inner Trim Board RH Clips - Set X nn	1	\$ 50.00	\$ 50.00
8	Radiator Coolant X nn	1	\$ 60.00	\$ 60.00
9	Front Bonnet Sealant X nn	1	\$ 150.00	\$ 150.00
10	Front Support Panel Sealant X nn	1	\$ 150.00	\$ 150.00
11	Front Fender RH Sealant X nn	1	\$ 150.00	\$ 150.00
12	Front Door RH Sealant X / APC	1	\$ 150.00	\$ 80 / 150.00
13	Front Tyre RH X nn	1	\$ 500.00	\$ 500.00
SPECIAL NETT TOTAL :				\$ 1,490.00

30

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts	\$ 500 2,000.00
2	To Spray Paint Affected Areas	\$ 700 1,800.00
3	Wiring & Bulb Check	\$ 30 100.00
4	To Transfer Front Door RH Mechanism	\$ 50 150.00
5	To Remove & Refix Aircon Condenser and Top Up Gas	\$ X 150.00
6	To Remove & Refix Radiator and Pressure Test	\$ X 150.00
7	To Remove & Refix Front Undercarriage	\$ X 500.00
8	To Remove & Refix Front Tyre and Conduct Wheel Balancing	\$ X 150.00
9	To Conduct Four Wheel Alignment	\$ 80 150.00
10	To apply anti rust on affected parts	\$ 30 120.00
11	To Conduct Water Leak Test	\$ X 100.00
12	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ 80 480.00
LABOUR TOTAL :		\$ 5,850.00

1470

Steve (LKK)
12/6/24, 12.00pm
w n
L/S
M A L M
5 dys

PARTS TOTAL :	\$	42,422.40
SPECIAL NETT TOTAL :	\$	1,490.00
LABOUR TOTAL :	\$	5,850.00
GRAND TOTAL :	\$	49,762.40

12,701.84

L/S - 10,161.47
= 10,150.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	10/06/2024 11:39 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	10/06/2024 07:55 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ALONG WOODLANDS AVENUE 10
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNJ412B
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	HUANG JIANKANG
NRIC No	SXXXX021A
Email Address	TIANBAORENOVATE@gmail.com
Mobile Phone No	(Phone) +65-83886038
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Lexus
Model	Es250
Variant	TOYOTA / LEXUS ES250 4DR SEDAN (AUTO) EXECUTIVE
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2487

INSURANCE COMPANY

Name of Insurance Company	Direct Asia Insurance (Singapore) Pte Ltd
Policy Number / Cover Note Number	MT/01369628

DRIVER

Name of Driver	HUANG JIANKANG
NRIC No	SXXXX021A
Date Of Birth	12/03/1968
Occupation	Outdoor

Pass Date	26/09/2017
Driving experience	6 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-83886038
Alt. Phone Number	-
Email Address	TIANBAORENOVATE@gmail.com
Address	APT BLK 653 WOODLANDS RING ROAD #04-470
Address complement	-
Postcode	730653
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE4147Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Goods vehicle
Name of Driver	-
Contact Number	-

...s complement
...code
...Insurance Company Name
...ature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

-
-
-
-
-
-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report promptly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the indorsement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of enveloped/paid parcels), and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/are be disclosed by any of the insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Actual Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel (please see in letter/O card)

Sketch Plan

Along Woodlands Avenue 10

A1: SM14118

A2: YE44PE TEL: 0654



www.gia.sg

Describe Circumstance of the Accident

On the stated time and date, I was driving Vehicle A, SNJ4128 when suddenly vehicle B, XE41472 side surge me from the right side, causing my right side mirror to come off and damaged the panel of fender and door.

Declaration
We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder)
/ Date & Time


Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

4 Jun 2022

2