



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24070097/Kqp3
(BUDGET DIRECT INSURANCE)	Date:	04/07/2024
190 CLEMENCEAU AVENUE #03-01		
SINGAPORE SHOPPING CENTRE SINGAPORE 239924	Code:	AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMQ 2987X	Veh. Inspected	SNP 2595L
Policy No.	-	Coverage	0
Claim No.	C10030355/KR	Excess	\$0.00
Assign From	MICHAEL	Assign Date	04/07/2024

2. Vehicle Details

Make & Model	NISSAN QASHQAI (A)	C.C	1332
Engine No.	HR13419500A	Year of Reg.	06/03/2023
Chassis No.	SJNTAAJ12U1071496	Colour	METALLIC BLACK
Odometer	25288 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/50R19	CONTINENTAL	9
L/H Front Tyre	235/50R19	CONTINENTAL	9
R/H Rear Tyre	235/50R19	CONTINENTAL	9
L/H Rear Tyre	235/50R19	CONTINENTAL	9

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/07/2024	Inspection Date	04/07/2024
Survey held at	HUI YANG MOTOR PTE LTD - BLOCK 176 SIN MING DRIVE #04-02 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days