



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL Ref: CS/AGI24070101/Unp3
(BUDGET DIRECT INSURANCE) Date: 08/08/2024
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRE SINGAPORE 239924 Code: AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGN 9112U	Veh. Inspected	SNC 5191S
Policy No.	-	Coverage	0
Claim No.	C10030341/JK	Excess	\$0.00
Assign From	MICHAEL	Assign Date	04/07/2024

2. Vehicle Details

Make & Model	HYUNDAI CN7 AVANTE (A)	C.C	1598
Engine No.	G4FMMU079590	Year of Reg.	27/10/2021
Chassis No.	KMHLN41ETNU238452	Colour	GREY
Odometer	32354 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/45R17	PIRELLI	7
L/H Front Tyre	225/45R17	PIRELLI	7
R/H Rear Tyre	225/45R17	PIRELLI	7
L/H Rear Tyre	225/45R17	PIRELLI	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/07/2024	Inspection Date	04/07/2024
Survey held at	15 KAKI BUKIT ROAD 4 BARTLEY BIZ CENTRE #01-53 - REPAIRER: ZOOM AUTOWEKRS PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days