

**MOTOR SURVEY ASSIGNMENT** 

**Date** 11/06/2024 **Our Ref No.** D24005164MFCT

Accident Date 09-06-2024 Claim Type Third Party

Insured Vehicle SHC1433S Third Party Vehicle SNL8840K

Survey Location NPH AUTO SERVICE Contact Person PEGGY

BLK 9005 TAMPINES STREET 93

#01-246/254 (S) 528839

**Contact No.** 67840663 **Fax No.** 

Survey Type Direct Settlement

(quantum to be agreed)

Appointed LKK AUTO CONSULTANTS PTE LTD

Surveyor

Contact Person Fax No. 68416315

Contact Number 62563561

## FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

Encl. Accident Reports & Estimate

Cc: Workshop NPH AUTO SERVICE Attention PEGGY

Officer Incharge NEOJIE

## **IMPORTANT NOTE**

Kindly submit the survey report by **email only** to <u>surveyor@msfirstcapital.com.sg</u> within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.