



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24070113/Uqp3
16 RAFFLES QUAY	Date:	05/07/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SH 7007T	Veh. Inspected	SLL 935Y
Policy No.	-	Coverage	0
Claim No.	D24005876MFCT	Excess	\$0.00
Assign From	BETTY	Assign Date	05/07/2024

### 2. Vehicle Details

Make & Model	CITROEN C4 PICASSO (A)	C.C	1560
Engine No.	10JBHD3057463	Year of Reg.	14/02/2017
Chassis No.	VF73DBHZTGJ715397	Colour	BLUE
Odometer	179882 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/60R16	MICHELIN	5
L/H Front Tyre	205/60R16	MICHELIN	5
R/H Rear Tyre	205/60R16	PIRELLI	5
L/H Rear Tyre	205/60R16	PIRELLI	5

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	03/07/2024	Inspection Date	05/07/2024
Survey held at	CARSMITH PTE LTD - 8 KAKI BUKIT AVE 4 #04-35 SINGAPORE 41587		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days