

ASSIGNMENT

From: _____ Date: _____

Estimate: _____

OD / TP RES / CD RES / EVA / INV / MV

To In _____ Vehicle No: _____

at V/O _____

of _____

Insured: _____

Policy: _____

Claims: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: The vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJK2356J Yr Regn: 2008 oct

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vios C.D. 1497

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 247320 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR053HY9305083828

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /

TOYO YOKO or

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / W/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I. 05/07/24

Zero Gravity

Front N/S

Date / Time

Action / Instruction

TP 1st Corp.

COE Expiry: 12/10/2028

Estimate given during: Yes ()

1st Survey: No ()

MV: 451K

PV: 13K

Nett: 32K

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

8 + RS. \$1

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

Report Format:

Report Format / L.P. / P.C.



ZG PTE LTD

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67477100/ 67412845

Reg.No.: 201317155Z

Quotation : QT-000096

MS FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

Attention: Motor Claim Department

TEL : 65073848/68543466

FAX : 65073849

Date In : 04/07/2024

Vehicle No. : SJK2356J

Make/Model : TOYOTA VIOS

Mileage(KM) : 247,320

Ref./Remark :

S/N	Quantity	Particular	Qty	U/ Price S\$	Amount S\$
1	1	PCS HEADLIGHT (L/H) <i>led</i>	1	PCS 738.20	✓ 738.20
2	1	PCS FOG LIGHT (L/H) <i>new</i>	1	PCS 463.70	✓ 463.70
3	1	PCS FOG LIGHT GARNISH <i>led</i>	1	PCS 146.60	✓ 146.60
4	1	PCS MOULDING (CHROME)(FOG LIGHT) <i>Missing</i>	1	PCS 160.25	✓ 160.25
5	1	PCS FENDER (L/H/F) <i>Bushed</i>	1	PCS 951.80	✓ 951.80
6	1	PCS FENDER INNER GARNISH (L/H/F) <i>toni</i>	1	PCS 249.35	✓ 249.35
7	10	PCS FENDER INNER GARNISH CLIP <i>new</i>	10	PCS 12.80	30 128.00
8	1	PCS EMBLEM "VVT" <i>new</i>	1	PCS 50.10	✓ 50.10
9	1	PCS FRONT BUMPER <i>Deland</i>	1	PCS 810.20	545 810.20
10	10	PCS BUMPER CLIP <i>new</i>	10	PCS 13.35	30 133.50
11	1	PCS BUMPER SIDE RETAINER (L/H/F) <i>crushed</i>	1	PCS 98.50	✓ 98.50
12	1	PCS FRONT BUMPER REINFORCEMENT <i>new</i>	1	PCS 398.00	✓ 398.00
13	1	PCS SUPPORT PANEL (L/H) (TOP) <i>new</i>	1	PCS 144.87	✓ 144.87
14	1	PCS SHOCK ABSORBER (L/H/F) <i>3m</i>	1	PCS 351.22	✓ 351.22
15	1	PCS SHOCK ABSORBER MOUNTING (L/H/F) <i>new</i>	1	PCS 229.35	✓ 229.35
16	1	PCS LOWER ARM (L/H/F) <i>Best</i>	1	PCS 577.45	✓ 577.45
17	1	PCS STEERING KNUCKLE (FRONT)(L/H) <i>long</i>	1	PCS 622.35	✓ 622.35
18	1	PCS FRONT WHEEL BEARING <i>led</i>	1	PCS 294.10	✓ 294.10
19		Discount 25 %			-1,636.89
20		SubTotal (L)			4,910.65
21	1	PCS SPORT RIM <i>led</i>	1	PCS 300.00	✓ 300.00
22	1	PCS TYRE <i>new</i>	1	PCS 180.00	✓ 180.00
23		SubTotal (S)			480.00
24	1	X PANEL BEAT & REPAIR FRONT DAMAGE	1	X 800.00	500 800.00
25	1	X TO PUTTY AND RE-SPRAY AFFECTED PORTION	1	X 900.00	600 900.00
26	1	X TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	1	X 60.00	30 60.00
27	1	X TO PROVIDE UNDER TURFCODE	1	X 120.00	30 120.00



ZG PTE LTD

2 Kaki Bukit Avenue 2, #01-25 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67477100/ 67412845

Reg.No.: 201317155Z

Quotation : QT-000096

MS FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

Attention: Motor Claim Department

TEL : 65073848/68543466

FAX : 65073849

Date In : 04/07/2024

Vehicle No. : SJK2356J

Make/Model : TOYOTA VIOS

Mileage(KM) : 247,320

Ref./Remark :

S/N	Quantity	Particular	Qty	U/ Price S\$	Amount S\$
28	1	X TO CHECK UNDERCARRIAGE AND REPLACE DAMAGED PARTS	1 X	300.00	180 300.00
29	1	X TO COMPUTERISE ADJUST WHEEL ALIGNMENT	1 X	100.00	80 100.00
30		SubTotal (LABOUR)			2,280.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
h/s 05/07/24
05 days

SINGAPORE DOLLAR SEVEN THOUSAND SIX HUNDRED SEVENTY AND CENTS SIXTY FIVE ONLY

E. & O.E

Total	S\$	7,670.65
Discount	S\$	0.00
Net Total	S\$	7,670.65

Terms: C.O.D.

Customer's Signature/Co. Stamp

ZG PTE. LTD.

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.