



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: CHARLOTTE CHEW

Ref: CS/INC24070116/Aqh3e2(N)

Date: 02/05/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 8161K	Veh. Inspected	GBE 4505J
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1284566-001	Excess (\$)	0.00
Assign From	CHARLOTTE CHEW	Assign Date	05/07/2024

2. Vehicle Particulars & Condition

Make & Model	NISSAB CABSTAR	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JN1SC2F24Z0857921	Colour	SILVER
Odometer	209379 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	HIFREE	6 mm
L/H Front Tyre	195 R15C	HIFREE	6 mm
R/H Rear Tyre	165 R13C	GREENLANDER	6 mm
L/H Rear Tyre	165 R13C	GREENLANDER	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/07/2024	Inspect Date / Time	05/07/2024 (04:34 PM)
Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	15 Working Days
-------------------------------------	-----------------