

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	INCOME INSURAN	ICE LTD		Ref:	CS/INC24070120/Aqh3m4(N)
	75 BRAS BASAH R INCOME CENTRES		Date:	10/07/2025	
	ATTN: YEE PEI LI			Code:	INC
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	PC 4147D	Veh. Inspected	t	YN 2945R
	Policy No.		Coverage (\$)		0.00
	Claim No.	MT/1284941-001	Excess (\$)		0.00
	Assign From	SITI RAUDHAH	Assign Date		05/07/2024
2. Vehicle Particulars & Condition					
	Make & Model	MITSUBISHI FE84BE6SRDEA	c.c		2977
	Engine No.	HIDDEN	Year of Reg.		2012
	Chassis No.	FE84BEA20252	Colour		WHITE
	Odometer	449356 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	7.00R16	WEST LAKE		6 mm
	L/H Front Tyre	7.00R16	WEST LAKE		6 mm
	R/H Rear Tyre	7.00R16	WEST LAKE		6 mm
	L/H Rear Tyre	7.00R16	WEST LAKE		6 mm
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
					§ *
5.	General Information				
	Accident Date	03/07/2024	Inspect Date /	Time	05/07/2024 ( 04:55 PM )
	Survey held at	JL PERFECT AUTOWORK PTE	LTD		
	8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		12 Work	ing Days
	•				