

ASSIGNMENT

From: _____ Date: _____

Estimate: _____

OD / TP RES / OD RES / EVA / INV / MV

To In Vehicle No: _____

at V/O _____

of _____

Insured: _____

Policy No: _____

Claim No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: Vehicle had commenced its

repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SAD3415B Yr Regn: 2016 August.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime mover /

Truck / Trailer or

Make: Hyundai i40 C.D. 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 1063739 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHLB41umGu093313

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: W / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: 205/60 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Giti

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 05/07/24

Survey held at Comfort Lorry

Des. of Damages: Frt / Rear O/S / N/S / U/C / Roof top or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TPMS/G</u>
	<u>COE Expiry :</u>
	<u>Estimate given during : Yes C ✓</u>
	<u>1st Survey : No C)</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

Effective Date: 1 Nov 2020

	YQ1171Y

MVA: **LIM T S**

$$\begin{array}{r} 300 \\ \cancel{400} \cancel{560} \\ \times 560 \end{array}$$

Adrian King
1/s 05/07/24. 3pm.
03 Days.

Hyundai i40

Date/Time: 04.07.2024 13:37

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5945649

JC NO305596633

STOMER /MS COMFORT TRANSPORTATION PTE LTD STOMER NO 7010045 DRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (O) (R) (P) COUNT CARD NO.	REGN NO: SHD3415B	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL I-40	DATE/TIME IN 04.07.2024 10:15
	YR OF MANU 18.08.2016 to 2025	TARGET DATE
	CHASSIS CODE KMHLB41UMGU093313	COMPLETION DATE/TIME:

JOB DESCRIPTION


dent Date: 04.07.2024

RE: 3P 04.07.2024/C

10

LABOR CODE
PB

DESCRIPTION
LUMP SUM REPAIR-SHD3415B-TP



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wedgement Slip

Exit Pass

No.: SHD3415B

LIMITS

Vehicle No.: SHD3415B

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard