

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
			Ref:	CS/FCI24070134/Unp3
	16 RAFFLES QUAY		Date:	21/08/2024
	#42-01 HONG LEON	NG BUILDING		
	SINGAPORE 04858		Code:	FCI2
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SHC 7337Y	Veh. Inspected	SLL 272B
	Policy No.	D-24101860MFCT	Coverage	0
	Claim No.	D24005911MFCT	Excess	\$0.00
	Assign From	JOANNE	Assign Date	08/07/2024
2. Vehicle Details				
	Make & Model	NISSAN QASHQAI 1.2 (A)	c.c	1197
	Engine No.	HRA2309742A	Year of Reg.	17/02/2017
	Chassis No.	SJNFEAJ11U1722480	Colour	BROWN
	Odometer	57168 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	215/60R17	YOKOHAMA	5
	L/H Front Tyre	215/60R17	YOKOHAMA	5
	R/H Rear Tyre	215/60R17	GOODYEAR	5
	L/H Rear Tyre	215/60R17	GOODYEAR	5
4.	4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
DAMAGES SEE DETAILS.				
5.	General Information			
	Accident Date	03/07/2024	Inspection Date	11/07/2024
	Survey held at	AUTOLUTION INDUSTRIAL PTE LTD 19 UBI ROAD 4 SINGAPORE 408623		
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days