



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24070135/Unp3
(BUDGET DIRECT INSURANCE)	Date:	08/07/2024
190 CLEMENCEAU AVENUE #03-01		
SINGAPORE SHOPPING CENTRE SINGAPORE 239924	Code:	AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMG 158M	Veh. Inspected	SNP 1233M
Policy No.	P10655172R02	Coverage	0
Claim No.	C10030379/HY	Excess	\$0.00
Assign From	CHANG SHI QIAN	Assign Date	08/07/2024

2. Vehicle Details

Make & Model	B.M.W. 318I (A)	C.C	1499
Engine No.	F4871793B38B15A	Year of Reg.	09/02/2018
Chassis No.	WBA8E36000NU81221	Colour	WHITE
Odometer	124582 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/50R17	MICHELIN	6
L/H Front Tyre	225/50R17	MICHELIN	6
R/H Rear Tyre	225/50R17	MICHELIN	6
L/H Rear Tyre	225/50R17	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/07/2024	Inspection Date	08/07/2024
Survey held at	BLK 15 KAKI BUKIT ROAD 4, BARTLEY BIZ CENTRE #01-53 - ZOOM AUTOWERKS PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days