



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: FIONA SHEN

Ref: CS/INC24070144/Anh3e2(N)

Date: 19/09/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SBJ 3773G	Veh. Inspected	SML 8712J
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1284033-002	Excess (\$)	0.00
Assign From	SITI RAUDHAH	Assign Date	09/07/2024

2. Vehicle Particulars & Condition

Make & Model	RENAULT SCENIC	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	VF1RFA00262894719	Colour	SILVER
Odometer	317093 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R20	GITI	6 mm
L/H Front Tyre	195/55 R20	GITI	6 mm
R/H Rear Tyre	195/55 R20	GITI	6 mm
L/H Rear Tyre	195/55 R20	GITI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/06/2024	Inspect Date / Time	09/07/2024 (02:58 PM)
Survey held at	HUI HUANG HONG BAO MOTORS 2 KAKI BUKIT AVENUE 2 #02-11 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------