



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24060046/Unp3m4
(BUDGET DIRECT INSURANCE)	Date:	12/06/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLV 9814B	Veh. Inspected	YQ 6134Y
Policy No.	P10882880R01	Coverage	0
Claim No.	C10029807/HY	Excess	\$0.00
Assign From	MICHAEL	Assign Date	12/06/2024

2. Vehicle Details

Make & Model	TOYOTA DYNA 150 (M)	C.C	2755
Engine No.	1GD8882729	Year of Reg.	22/03/2022
Chassis No.	JHHAGV4640K001911	Colour	SILVER
Odometer	112169 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	175/75R15	BRIDGESTONE	3
L/H Front Tyre	175/75R15	BRIDGESTONE	3
R/H Rear Tyre	155R13 (D)	YOKOHAMA	7
L/H Rear Tyre	155R13 (D)	YOKOHAMA	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/06/2024	Inspection Date	13/06/2024
Survey held at	FOCUS AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #02-50 KAKI BUKIT @ AUTOBAY		

5a. Remarks
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days