

(08/11/13) Wef

ASS. REC. BY:

REF:

CO/FCI24070148/Rua3

8002

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SNP97683

at Workshop m/s Komoco

of ALEXANDRA RD

Insured:

FCI2

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

170K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNP97683

Yr Regn:

2024 / MGR

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HYUNDAI SX2 KONA / 1.6 SR cc 1580

Colour:

RED

A/C: Insured / Std / NI / NA

Sp. Reading:

7073

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMHHG811VRU037034

Gen. Cond: Good / Fair / Poor / Burnt

Steering: in order / Jammed / Leaked / Burnt or

Brake: in order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

NEXEN

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

05/07/24

D.O.I.

09/07/24

Survey held at

ALEXANDRA

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT-63K

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) \$+RS \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

11ab 5/7 ms.

Date :

MS FIRST CAPITAL Insurance Pte Ltd
Attn: Motor Claims Department

Vehicle number : **SNP9768J**
Make and model : **KONA ELECTRIC**
Registration Date : **25/03/2024**
Chassis number : **KMHHE811VRU037034**
Engine number : **G4LLPS264781**

Claim Officer : **Robyn**
Job No. :
Owner name : **KHALID BIN AHM.**
Date of Acc : **05/07/2024**
Policy number : **A301105154 AH1**
Claim Type : **TP**

Items :			2nd	Estimate	Revised
1	FRONT BUMPER CLIP X10 <i>m /</i>	865952T500		\$ 20.00	
2	COVER ASSY-FR BUMPER UPR <i>sun /</i>	86510BE100		\$ 726.00	
3	COVER ASSY-FR BUMPER LWR <i>sun /</i>	86560BE110		\$ 1,100.00	
4	BRACKET ASSY-FR BUMPER SIDE,LH <i>?</i>	86551BE000		\$ 20.00	
5	BRACKET ASSY-FR BUMPER SIDE,RH <i>?</i>	86552BE000		\$ 20.00	
6	LAMP ASSY-HEAD,LH <i>sun /</i>	92101BE130		\$ 2,759.00	
7	CLIP (X 3) <i>m /</i>	1420608250B		\$ 3.00	
8	GUARD ASSY-FRONT WHEEL,LH <i>?</i>	86811BE000		\$ 175.00	
9	MOULDING-FRONT BUMPER,LH <i>?</i>	86595BE000		\$ 74.00	
				\$ 4,897.00	
Less 25% Discount				\$ 1,224.25	
Material total				\$ 3,672.75	

Vehicle number : SNS9616Z

Body, Paint & Labour Items :

Estimate

- | | | | | |
|---|---|----|----------|-----|
| 1 | To carry out accident body repair - FRONT BUMPER | \$ | 1,280.00 | 420 |
| 2 | Complete putty and spray paint all affected areas - FRONT BUMPER / FRONT BUMPER GARNISH | \$ | 1,050.00 | 350 |

Labour Charges:

2nd

Estimate

Revised

- | | | | | |
|---|--|----|--------|----|
| 3 | TO REALIGN BOTH FRT HEADLAMP (S.NETT) | \$ | 40.00 | X |
| 4 | TO PERFORM WHEEL ALIGNMENT (S.NETT) | \$ | 140.00 | X |
| 5 | TO CHECK FOR ELECTRICAL SYSTEM FOR PROPER FUNCTIONING AFTER AC | \$ | 180.00 | ✓ |
| 6 | TO REPROGRAMME AFTER ACCIDENT REPAIR (S.NETT) | \$ | 180.00 | ✓ |
| 7 | SUNDRIES (S.NETT) | \$ | 40.00 | 20 |

Total Labour

\$ 2,890.00 \$ -

Total Parts

\$ 3,672.75 \$ -

Excess

\$ - \$ -

\$ 6,562.75 \$ -

Add GST 9%

\$ 590.65 \$ -

Grand Total

\$ 7,153.40 \$ -

*** Estimation are base on visual inspection, should there be furthur damages found during process of repair, you will be inform prior before carry out***

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rashid
Ap 90010068
3 day
P/P
09/07/24
Resy after paint

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	800I
Vehicle Details	
Vehicle No.:	SNP9768J
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jul 2024
Vehicle Make:	HYUNDAI
Vehicle Model:	SX2 KONA 1.6 GDI HEV SR
Primary Colour:	Red
Manufacturing Year:	2023
Engine No.:	G4LLPS264781
Chassis No.:	KMHHE811VRU037034
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$29,538.00
Original Registration Date:	25 Mar 2024
First Registration Date:	25 Mar 2024
Transfer Count:	0
Actual ARF Paid:	\$28,354.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Mar 2034
PARF Rebate Amount:	\$21,265.00
Intended COE Rebate Details	
COE Expiry Date:	24 Mar 2034
COE Category:	A - Car-Details at OneMotoring
COE Period(Years):	10
QP Paid:	\$88,020.00
COE Rebate Amount:	\$85,417.00
Total Rebate Amount:	\$106,682.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 10 Jul 2024

OK



Hyundai Kona Hybrid

\$178,999 - \$190,999



Overview Photo Review Promo Compare

Distributor	Komoco Motors
	6475 8888
Built in	Korea (launched 2023)
Predecessor	> Hyundai Kona Electric (2019-2023)
Rating	★★★★☆ 2 reviews

Pricelist

Brochure

Shortlist

SUBMODELS

1.6 GL (A)

Cat A | 129 bhp | 21.3 km/L

\$178,999

\$16,800 /yr



☒ Compare

Pricing

Specs

Features

Call

Messenger