

ASS. REC. BY:

REF: /

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / P / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

01 days

Res.: Yes or No

Lum Sum:

145.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

WD 5033 D Yr Regn: 12, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

UD Truck

C.C.

10836

Colour

White Blk

A.C:

Insured / Std / NI / NA

Sp. Reading

P1975

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JNEMBPOG9KU044182

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: M / S / R / m / STD A / R / m or

Tyre Size:

F:

295/80R22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Firm 80

Front

R/Bal.

9 3

mm

L/Bal.

9 3

mm

D.O.A.

4/7/24

Rear

R/Bal.

66 88

L/Bal.

66 88

D.O.I.

10/7/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rt RH wing mirror

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Data/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Data/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

) \$ - RS. SI

) P. 100

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

AUTOEXCEL ENGINEERING PTE LTD

HANDPHONE 90030857

Date : 10 Jul 2024

QUOTATION - THIRD PARTY CLAIM

SINGAPORE POLICE FORCE

CLAIM : THIRD PARTY CLAIM

DATE ACCIDENT : 4 Jul 2024

VEH. No : WD 5033 D / UD TRUCK

ATTN : MOTOR CLAIM DEPARTMENT

INSURE : INCOME INSURANCE

QTY	ITEM	AMOUNT	CONDITION
-----	------	--------	-----------

Third party vehicle : YQ 3164 E

1	RH SIDE MIRROR	\$ nd/cm 980.00	✓
1	RH SIDE MIRROR STAND	\$ R D 480.00	✗
TOTAL PARTS :		\$ 1,460.00	
LESS 10%		\$ 146.00	
TOTAL LIST PARTS :		\$ 1,314.00	
TOTAL PARTS PRICE :		\$ 1,314.00	

AMOUNT BRING FORWARD :

\$ 1,314.00

Labour charges	\$ 200.00	10d
check wiring system	\$ 120.00	15h
TOTAL LABOUR :	\$ 320.00	
GRAND TOTAL PARTS & LABOUR :	\$ 1,634.00	

NOT Whairu
Runny After pain
1 day

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

te: