Ass't: Entry: Ref: CS/FCI24070171/Avp3

ASSIGNMENT

From: Date:

Estimate/Cost:

OD / TPFT / TP RES / CD RES / EVA / INV / MV

To Inspect Vehicle No:

at WORKSHOP/s

of

Insured: SH 8780L

Policy No:

Claims No: D24005966MFCT

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PP Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMM45OL Yr Regn: 2019, June.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Fit C.C 1317

Colour Blue. A/C: Insured / Std / NI / NA

Sp.Reading 125870 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GK33415884

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/70R14

R: 175/70R14.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.	5/7/2024	D.O.I.	09/07/24.

Survey held at Auto United

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP 1st Cap: COE Expiry :
7/10/24	Adrian confirmed LS $23,500 (Red 12,294.32, 34%)
	Estimate given during : Yes ( )
	1st Survey : No (✓)
	MV : 68K
	PV : 17.5K
	Nett : 50.5K
	64SA.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 21

Resurvey No. of Trip:

Addl Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Inve ($)

Survey Fee:

Transportation: ___$ + RS___$

Photos

Others

Report Format :