



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24070175/Knp3e2
(BUDGET DIRECT INSURANCE)	Date:	01/08/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMX 1405D	Veh. Inspected	SLB 4461Z
Policy No.	P11012160R00	Coverage	0
Claim No.	C10030386/CY	Excess	\$0.00
Assign From	MICHAEL	Assign Date	09/07/2024

2. Vehicle Details

Make & Model	B.M.W. 216I GRAN TOURER	C.C	1499
Engine No.	37186091B38A15A	Year of Reg.	06/10/2020
Chassis No.	WBA6V120805R85615	Colour	METALLIC DARK BLUE
Odometer	69036 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/55R17	MICHELIN	6
L/H Front Tyre	205/55R17	MICHELIN	6
R/H Rear Tyre	205/55R17	MICHELIN	6
L/H Rear Tyre	205/55R17	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	05/07/2024	Inspection Date	22/07/2024
Survey held at	ALAN'S UNITED AUTO PTE LTD - BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days