



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24070183/Unh3
75 BRAS BASAH ROAD	Date:	10/07/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJY 9540Z	Veh. Inspected	GBF 2232D
Policy No.	-	Coverage	0
Claim No.	MT/1285152-002	Excess	\$0.00
Assign From	HELENA TAN	Assign Date	10/07/2024

2. Vehicle Details

Make & Model	NISSAN NV200 (M)	C.C	1461
Engine No.	K9KC400D055735	Year of Reg.	29/07/2016
Chassis No.	VSKYBAM20Z0127745	Colour	GREY
Odometer	236854 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	175/70R14	KAPSEN	5
L/H Front Tyre	175/70R14	KAPSEN	5
R/H Rear Tyre	175/70R14	HABILEAD	5
L/H Rear Tyre	175/70R14	HABILEAD	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/07/2024	Inspection Date	10/07/2024 (10:12)
Survey held at	ZG PTE LTD - 2 KAKI BUKIT AVENUE 2 #01-25 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days