

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS	INCOME INSURAN		Ref:	CS/INC24070184/Aqh3m4
	75 BRAS BASAH RO	OAD SINGAPORE 189557	Date:	24/10/2024
	INCOME CENTRE	SINO, II ONE 100007	Code:	INC
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SNB 7856A	Veh. Inspected	SLK 7286X
	Policy No.	-	Coverage	0
	Claim No.	MT/1285450-001	Excess	\$0.00
	Assign From	SHAFAWATI BINTE MD RABU	Assign Date	10/07/2024
2. Vehicle Details				
	Make & Model	VOLVO V40	C.C	1498
	Engine No.	B4154T51898561	Year of Reg.	25/01/2017
	Chassis No.	YV1MV28H0H2412201	Colour	GREY
	Odometer	96812 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	205/55R16	YOKOHAMA	6
	L/H Front Tyre	205/55R16	YOKOHAMA	6
	R/H Rear Tyre	205/55R16	YOKOHAMA	6
	L/H Rear Tyre	205/55R16	YOKOHAMA	6
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5.	General Information			
	Accident Date	08/07/2024	Inspection Date	10/07/2024 (11:56)
	Survey held at JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				